



New Goon Motor
 Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not withstanding
C1 Ray @ 3450/r
Penny after Penny
5 days

Policy No: _____

Date: 03.08.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity		货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Mitsubishi Lancer EX" Reg. No. SFC3209J Claiming Against Your Insured Veh. No. SMQ7625H				
1pc		Rear Door LH	4.50	935.00
1pc		Rear Door Weatherstrip		140.60
10pcs		Rear Door Trim Board Clips		45.00
1pc		Rocker Panel LH		652.00
1pc		Rear Wheel Rim		934.00
1pc		Rear Wheel Bearing	3.00	453.00
1pc		Rear Bumper		876.00
14pcs		Rear Bumper Clips		42.00
1pc		Rear Bumper Corner Retainer LH		20.70
		Less 10%		
				409.83
				3,688.47
		Rear Door Visor		180.00
		Rear Door Visor Chrome Moulding		120.00
		Rear Door Inner Insulation		150.00
		Rocker Panel Top Step Scuff Plate		180.00
		Rear Tyre		295.00
		To Dismantle / Transfer Rear Door Fittings / Ancillary Accessories		150.00
		To Supply Rear Fender Body Sealant		60.00
		To Replace Rear Wheel Bearing		100.00
		To Conduct Computerize Wheel Alignment Test		80.00
		To Conduct High Speed Balancing		80.00
		To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00
		Labour Charge - Panel Beating, Repairing Of Rear Fender, Rocker Inner Panel, Floor Panel etc. Cnt, Weld Rocker Panel And Part Replacement.		900.00
		To Respray Affected Areas		
Total :				900.00
				6,983.47