

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
 HP: 8386 8989 Email: atautoconsultant@gmail.com
 Co. Reg. No.: S33485268

Date of Estimate: 05.08.2021
 Vehicle No: SMT7377H
 Owner: MAHENDRAN S/O NITHIA ANNATHAN
 Date of Accident: 29.07.2021
 Make & Model: BMW 420i
 Chassis No : WBA4532060AG24647

*Not Authorized
 L1Ry @ 1600h
 Resurvey After Repair
 2 days*

ESTIMATE FOR ACCIDENT VEHICLE NOS SMT7377H

PARTS

- | | | |
|---|----------------------------|-----|
| 1 | 1 Bumper front | |
| 2 | 1 Fog lamp garnish RH | 326 |
| 3 | 1 Head lamp RH | |
| 4 | 1 Fender front RH (repair) | |

SUB TOTAL
 LESS 10%
 DISCOUNTED SUB TOTAL

Avul Co \$1,355.00 ✓
nd/Co \$489.00 ✓
in \$2,839.00 X
 \$0.00
 \$4,683.00
 \$468.30
 \$4,214.70

S. NETT ITEM

- | | |
|---|-----------------------------|
| 1 | 1set Front bumper clips |
| 2 | 1 Front bumper Sensor X 1pc |

SUB TOTAL
 LESS 0 %
 DISCOUNTED SUB TOTAL

in \$50.00 ✓
in \$280.00 X
 \$330.00
 \$0.00
 \$330.00

LABOUR

- | | |
|---|---|
| 1 | Panel beating for replace and repair affected parts |
| 2 | Spray painting on accident areas |
| 3 | Wiring charges |
| 4 | Apply undercoating to above affected areas |
| 5 | 4 wheel alignment |

SUB TOTAL (LABOUR)

\$500.00 2206
 \$600.00 2506
 \$100.00 156
in \$80.00 X
in \$120.00 X
 \$1,400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: