

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0631/2021/ZK  
**DATE** : 4-Aug-21  
**WIP** : 38265

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 10/8/2021**

**YOUR INSURED VEH NO : SLC 4686 L**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Adrian**

**4 days - ok - Johnny Boo**

**15-Oct-21**

**OWNER'S NAME** : MT TAN DEON WEI KIANG  
**ADDRESS** : BLK 123 SERANGOON NORTH AVE 1  
#12-157  
SINGAPORE 550123  
**TELEPHONE** : HP +65 9178 8320  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 2070134287  
**VEHICLE NO** : **SMV 3233 E**  
**MODEL CODE** : AUDI Q3 1.4 TFSI S  
**MODEL YEAR** : 25/9/2020  
**ENGINE NO** : CZD C04288  
**CHASSIS NO** : WAUZZZF30M1005182  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 3-Aug-21  
**PLACE OF ACCIDENT** : ORCHID COUNTRY CLUB CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

### **ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 3233 E**

| <b>S/N</b>                  | <b>NATURE OF JOBS</b>                                                                                                                           |        | <b>ESTIMATED<br/>CHARGES</b> | <b>SURVEYOR'S<br/>RECOMMENDATIONS</b> |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|--------|------------------------------|---------------------------------------|
| 1                           | TO REMOVE , CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ | 480.00                       | \$ <b>480.00</b>                      |
| 2                           | TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                           | S/N \$ | 400.00                       | \$ <b>250.00</b>                      |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER , RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.   | \$     | 2,400.00                     | \$ <b>1,000.00</b>                    |
| 4                           | TO RESPRAY FRONT BUMPER AND RHS FRONT FENEDER                                                                                                   | \$     | 2,200.00                     | \$ <b>1,100.00</b>                    |
| 5                           | TO REAPPLY PAINT COATING ON AFFECTED AREA (BY OWNER)                                                                                            | S/N \$ | 280.00                       | \$ <b>280.00</b>                      |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                 | :      | <b>\$ 5,760.00</b>           | <b>\$ 3,110.00</b>                    |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 3233 E**

| S/N                         | NATURE OF JOBS                                   |            | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------|------------|----------------------|-------------------------------|
|                             |                                                  | <i>c/f</i> |                      | \$ 3,110.00                   |
| 6                           | TO REAPPLY HEADLIGHT PROTECTTION FILM (BY OWNER) | S/N \$     | 250.00               | \$ 208.00                     |
| 7                           | TO CARRY OUT DIAGNOSTIC CHECK                    | S/N \$     | 192.00               | \$ 192.00                     |
| <b>TOTAL LABOUR CHARGES</b> |                                                  | :          | \$ 6,202.00          | \$ 3,510.00                   |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)
**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 3233 E**

|                             |                                    |     | DAMAGED PARTS & PRICES |           |                  |
|-----------------------------|------------------------------------|-----|------------------------|-----------|------------------|
| S/N                         | PARTS DESCRIPTION                  | QTY | S/NETT                 | REMARKS   |                  |
| 1                           | FRONT BUMPER                       | 1   | \$ 1,008.00            | \$        | 806.40           |
| 2                           | FRONT BUMPER CLOSING ELEMENT - RH  | 1   | \$ 59.00               |           |                  |
| 3                           | FRONT BUMPER LOWER GRILLE - RH     | 1   | \$ 110.00              |           |                  |
| 4                           | FRONT BUMPER LOWER CLOSING ELEMENT | 1   | \$ 190.00              |           |                  |
| 5                           | FRONT BUMPER SPOILER               | 1   | \$ 383.00              | \$        | 306.40           |
| 6                           | FRONT BUMPER AIR GRILL - RH        | 1   | \$ 153.00              |           |                  |
| 7                           | FRONT BUMPER GUIDE SECTION - RH    | 1   | \$ 39.00               | \$        | 30.48            |
| 8                           | FRONT BUMPER TOP COVER             | 1   | \$ 123.00              |           |                  |
| 9                           | CAUTION STICKER                    | 1   | \$ 14.00               |           |                  |
| 10                          | AIR-CONDITIONER STICKER            | 1   | \$ 8.00                |           |                  |
| 11                          | FRONT FENDER - RH                  | 1   | \$ 1,286.00            | \$        | 1,028.80         |
| 12                          | FRONT FENDER ATTACHEMENT PART -RH  | 1   | \$ 63.00               |           |                  |
| 13                          | FRONT FENDER BRACE - RH            | 1   | \$ 88.00               | \$        | 69.76            |
| 14                          | FRONT FENDER BRACKET - RH          | 1   | \$ 32.00               |           |                  |
| 15                          | FRONT PARKING AID SENSOR           | 1   | TBC                    |           |                  |
| 16                          | FRONT PARKING AID SENSOR SEAL      | 4   | \$ 14.00               |           |                  |
| 17                          | HEADLIGHT MOUNTING - RH            | 1   | \$ 118.00              |           |                  |
| 18                          | HEADLIGHT - RH                     | 1   | \$ 5,589.00            | \$        | 4,471.20         |
| 19                          | HEADLIGHT WASHER CYLINDER - RH     | 1   | \$ 210.00              |           |                  |
| 20                          | FRONT WHEEL ARCH COVER - LH / RH   | 2   | \$ 536.00              | \$        | 428.80           |
| 21                          | SUNDRIES                           | S/N | \$ 350.00              |           |                  |
| <b>TOTAL SPARE PARTS</b>    |                                    |     | <b>\$ 10,373.00</b>    | <b>\$</b> | <b>7,141.84</b>  |
| <b>TOTAL LABOUR CHARGES</b> |                                    |     | <b>\$ 6,202.00</b>     | <b>\$</b> | <b>3,510.00</b>  |
| <b>GRAND TOTAL</b>          |                                    |     | <b>\$ 16,575.00</b>    | <b>\$</b> | <b>10,651.84</b> |

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.  
 bi-30/09/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT