

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0631/2021/ZK
DATE : 4-Aug-21
WIP : 38265

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 10/8/2021

YOUR INSURED VEH NO : SLC 4686 L

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MT TAN DEON WEI KIANG
ADDRESS : BLK 123 SERANGOON NORTH AVE 1
#12-157
SINGAPORE 550123
TELEPHONE : HP +65 9178 8320
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070134287
VEHICLE NO : **SMV 3233 E**
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 25/9/2020
ENGINE NO : CZD C04288
CHASSIS NO : WAUZZZF30M1005182
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 3-Aug-21
PLACE OF ACCIDENT : ORCHID COUNTRY CLUB CARPARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 3233 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING, ATD	S/N \$	480.00 ✓	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00 250 ✓	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER , RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	\$	2,400.00 1000 ✓	✓
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	\$	2,200.00 1100 ✓	✓
5	TO REAPPLY PAINT COATING ON AFFECTED AREA (BY OWNER)	S/N \$	280.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u>\$ 5,760.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 3233 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REAPPLY HEADLIGHT PROTECTION FILM (BY OWNER)	S/N \$	250.00 ✓	208.00
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00 ✓	✓
TOTAL LABOUR CHARGES		:	\$ 6,202.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 3233 E

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER <i>reh 2</i>	1	\$ 1,008.00	✓	806.40	
2	FRONT BUMPER CLOSING ELEMENT - RH <i>neu</i>	1	\$ 59.00	✗		
3	FRONT BUMPER LOWER GRILLE - RH <i>neu</i>	1	\$ 110.00	✗		
4	FRONT BUMPER LOWER CLOSING ELEMENT <i>neu</i>	1	\$ 190.00	✓	306.40	
5	FRONT BUMPER SPOILER <i>lit</i>	1	\$ 383.00	✓		
6	FRONT BUMPER AIR GRILL - RH <i>neu</i>	1	\$ 153.00	✗		
7	FRONT BUMPER GUIDE SECTION - RH <i>cracked</i>	1	\$ 39.00	✓	30.48	
8	FRONT BUMPER TOP COVER <i>neu</i>	1	\$ 123.00	✗		
9	CAUTION STICKER <i>neu</i>	1	\$ 14.00	✗		
10	AIR-CONDITIONER STICKER <i>neu</i>	1	\$ 8.00	✗		
11	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,286.00	✓	1,028.80	
12	FRONT FENDER ATTACHEMENT PART -RH <i>Not Nec</i>	1	\$ 63.00	✗		
13	FRONT FENDER BRACE - RH <i>bent</i>	1	\$ 88.00	✓	69.76	
14	FRONT FENDER BRACKET - RH <i>neu</i>	1	\$ 32.00	✗		
15	FRONT PARKING AID SENSOR <i>Not Nec</i>	1	TBC	✗		
16	FRONT PARKING AID SENSOR SEAL <i>neu</i>	4	\$ 14.00	✗		
17	HEADLIGHT MOUNTING - RH	1	\$ 118.00	✗		
18	HEADLIGHT - RH <i>lit</i>	1	\$ 5,589.00	✓	4,471.20	
19	HEADLIGHT WASHER CYLINDER - RH <i>neu</i>	1	\$ 210.00	✗		
20	FRONT WHEEL ARCH COVER - LH / RH <i>Lit Nec, Rlt lit</i>	2	\$ 536.00	✓	428.80	
21	SUNDRIES <i>?</i> Not Nec	S/N	\$ 350.00	✗		
TOTAL SPARE PARTS		:	\$ 10,373.00			
TOTAL LABOUR CHARGES		:	\$ 6,202.00			
GRAND TOTAL		:	\$ 16,575.00			

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *11/08/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *are Authorised , 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT