

# Massive Trading & Auto

Mailing address : Blk 225 #01-405 Ang Mo Kio Ave 1 Singapore 560225  
H/p 91082728

Fax : 64816131

Mohd Hairi Bin Adinan  
733 Jurong West St 72  
#05-30  
Singapore 640733

Vehicle No : SMK 3087 T  
Make : Kia Cerator  
Year : 2019

*Not Notation  
1/1000 \$ 6.900p  
Repair After Paint  
7 days*

Qty	Description	Unit Price	Amount
<u>Estimate Cost Of Repair</u>			
2 pcs	Rear fender	\$1,133.00	\$2,266.00 X
2 pcs	Rear fender inner trim	CM \$255.00	\$510.00 ✓
1 pc	Rear windscreen moulding	SM \$95.00	\$95.00 X
1 pc	Rear boot lid 1255	BY \$1,497.00	\$1,497.00 ✓
2 pcs	Rear no plate lamp	SM \$45.00	\$90.00 X
2 pcs	Rear boot lid lamp assy e608	MS/M3CM \$697.00	\$1,394.00 ✓
1 pc	Rear boot lid centre reflector	SM \$608.00	\$608.00 X
1 pc	Rear boot lid inner lock	MS \$165.00	\$165.00 ✓
1 pc	Rear boot lid emblem " Logo "	MS \$45.00	\$45.00 ✓
1 pc	Rear boot lid emblem " Cerator "	MS \$48.00	\$48.00 ✓
2 pcs	Rear tail-lamp assy e6f5	MS/M3CM \$675.00	\$1,350.00 ✓
2 pcs	Rear tail-lamp panel	R \$159.00	\$318.00 X
1 pc	Rear boot rubber	74.50W \$149.00	\$149.00 508in
1 pc	Rear end panel 349	BY \$495.00	\$495.00 ✓
1 pc	Rear end panel inner garnish	BY \$125.00	\$125.00 ✓
1 pc	Rear bumper	BUL/CM \$688.00	\$688.00 ✓
1 pc	Rear bumper lower garnish	CM \$296.00	\$296.00 ✓
2 pcs	Rear bumper reflector	SM \$181.00	\$362.00 X
2 pcs	Rear bumper bracket	\$105.00	\$210.00 X
2 pcs	Rear bumper side retainer	\$55.00	\$110.00 X
1 pc	Rear bumper reinforcement 343-20	BY \$392.00	\$392.00 ✓
1 pc	Rear spare tyre panel	R \$595.00	\$595.00 X
1 pc	Rear spare tyre panel top cover board	CM \$317.00	\$317.00 ✓
			\$12,125.00
		Less 10 %	\$1,212.50
			\$10,912.50

balance c/f \$10,912.50

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ASS. REC. BY:

REF:

Asm/

ASS. REC. BY:

REF:

Te

BII

SMK 3087 T

balance b/f \$10,912.50

S. Nett Item

1 pc Rear boot lid top spoiler  
 1 pc Rear no plate " Weekend "  
 1 pc Rear no plate seal  
 1 pc Rear windscreen sealant  
 15 pcs Rear bumper clip  
 1 pc Rear reverse sensor

Net \$450.00 ✓  
 Net \$35.00 } 455m  
 Net \$20.00 }  
 Net \$40.00 X  
 Net \$30.00 ✓  
 Net \$200.00 ✓  
 \$2.00  
 \$775.00

Labour Charges

Remove/renew the above parts including knocking, cutting &amp; welding.

\$1,400.00 980l

To putty &amp; spray paint on accident affected portion.

\$1,200.00 1000l

Check/reconnect wiring.

\$45.00 20l

To spray anti rust on accident affected portion.

\$150.00 60l

Remove/refit rear boot upholstery to facilitate repair.

\$120.00 100l

Remove/renew rear windscreen to facilitate repair.

~~ \$120.00 X

Remove/refit fuel tank to facilitate repair.

~~ \$100.00 X

Remove/refit roof lining to facilitate repair.

~~ \$180.00 X

Total \$15,002.50