



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2202159
3 ANSON ROAD #16-00	INV Date	14/04/2022
SPRINGLEAF TOWER	Reference	CC6/CTI21008226/Uga3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SMP 1210R
Insured Veh.	GBJ 6147U
Claim No.	SNM21D204335
Policy No.	DMCVBNW00058452102
Accident Date	03/08/2021
Inspection Date	04/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21008226/Uga3q2 Date: 14/04/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBJ 6147U	Veh. Inspected	SMP 1210R
Policy No.	DMCVBNW00058452102	Coverage (\$)	0.00
Claim No.	SNM21D204335	Excess (\$)	0.00
Assign From		Assign Date	04/08/2021
2. Vehicle Particulars & Condition			
Make & Model	RENAULT FLUENCE (A)	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1LZLF0E54200158	Colour	BEIGE
Odometer	66917 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/08/2021	Inspection Date	04/08/2021
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 1210R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEEP CUT	1,655.10	1,415.23
1	FRONT BUMPER SIDE RETAINER O/S	NOT NECESSARY	66.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	685.00	-
1	HEADLAMP O/S	CRACKED	1,255.10	1,255.10
1	HEADLAMP LOWER BRACKET O/S	CRACKED	288.50	185.42
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	655.20	-
1	FRONT FENDER INNER SHIELD O/S	NOT NECESSARY	155.20	-
	LESS 10% DISCOUNT		-	-290.58
			4,810.10	2,615.17
LABOUR				
	TO CHECK WIRING .		50.00	20.00
	TO SPRAY RUST PROOFING .	NOT NECESSARY	50.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING &REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER O/S .		480.00	250.00
	TO PUTTY & SPRAY PAINTING.		680.00	400.00
			1,360.00	670.00
GRAND TOTAL			6,170.10	3,285.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,600.00

Report Ref No. CC6/CTI21008226/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 1210R

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMP 1210R

RE-INSPECTION

