



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21008228/Atf3n2	Date: 15/12/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKN 896C	Veh. Inspected	SLK 3644Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10011131/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	04/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180K	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	WDD2040462A092010	Colour	BLACK	
Odometer	124286 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	GITI	6 mm	
L/H Front Tyre	225/45 R17	GITI	6 mm	
R/H Rear Tyre	225/45 R17	GITI	6 mm	
L/H Rear Tyre	225/45 R17	GITI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/07/2021	Inspection Date	26/08/2021	
Survey held at	TK MOTOR WORKSHOP 1 KAKI BUKIT AVENUE 6, #02-56, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	