

Estimation

Date _____
Vehicle _____ SJL 3657 D
Make/Model _____ MITSUBISHI LANCER
Chassis No. _____ JMYSTCS3A8U010591

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	FRONT WIPER PANEL GARNISH x	1	\$	-
2	BONNET HINGE x	2	\$	-
3	HEADLAMP L+R <i>by car / Hx</i>	2	\$	-
4	HEADLAMP BRACKET L+R <i>RM, LH x</i>	2	\$	-
5	FRONT BUMPER RETAINER L+R x	2	\$	-
6	FRONT BUMPER REINFORCEMENT BAR <i>by</i>	1	\$	-
7	FRONT BUMPER SPONGE x	1	\$	-
8	FRONT BUMPER UNDERCOVER x	1	\$	-
9	FRONT FENDER L+R x	2	\$	-
10	FRONT FENDER COWLING L+R <i>in</i>	2	\$	-
11	FRONT SUPPORT PANEL <i>by</i>	1	\$	-
12	FRONT SUPPORT PANEL TOP GARNISH x	1	\$	-
13	AIRCON CONDENSOR ?	1	\$	-
14	AIRCON CONDENSOR AIR GUIDE L+R x	2	\$	-
15	RADIATOR x	1	\$	-
16	RADIATOR FAN COWLING x	1	\$	-
17	RADIATOR FAN BLADE x	1	\$	-
18	RADIATOR FAN MOTOR x	1	\$	-
19	WIPER WASHER TANK x	1	\$	-
20	FRONT HORN <i>by</i>	1	\$	-
			Total	\$ -
			Less 10%	\$ -
			Total	\$ -

	S/Nett Items				
1	BONNET CARBON FIBRE	1	4000	\$ x	4,000.00
2	BONNET INSULATOR	1	200	\$ x	200.00
3	FRONT GRILLE	1	900	\$ <i>car 200</i>	900.00
4	FRONT BUMPER TOP	1	2000	\$ <i>de</i>	2,000.00 <i>800</i>
5	FRONT BUMPER LOGO - MITSUBISHI	1	200	\$ x	200.00
6	FRONT BUMPER LOWER	1	2500	\$ <i>Ry</i>	2,500.00
7	FRONT BUMPER FOG LAMP L+R	2	400	\$ x	800.00
8	FRONT BUMPER TAG	1	250	\$ x	250.00
9	FRONT BUMPER CLIPS	1	100	\$ <i>30</i>	100.00
10	FRONT NUMBER PLATE	1	120	\$ <i>45 by</i>	120.00
11	FRONT FENDER COWLING CLIPS	2	100	\$ <i>30</i>	200.00

12	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1	100	\$ X	100.00
13	RADIATOR COOLANT	1	100	\$ X	100.00
			Total	\$	11,470.00

	LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	1400	\$ 700	1,400.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1500	\$ 500	1,500.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$ 30	150.00
4	TO CHECK WIRING AND FOG LAMP FUNCTION	1	150	\$ X	150.00
5	TO RNR INNER TRIM AND UPHOLSTERY	1	400	\$ X	400.00
6	TO CHECK WATER LEAK	1	150	\$ X	150.00
7	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	1	300	\$ 100 ?	300.00
8	TO RNR FRONT RADIATOR	1	250	\$ X	250.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$ X	600.00
10	TO PERFORM RUST PROOFING	1	200	\$ 30	200.00
11	TO RNR HORN AND TEST FUNCTION	1	150	\$ X	150.00

Total Labour	\$	5,250.00
Parts Replacement Amount	\$	11,470.00
Total Amount	\$	16,720.00

Tanjir 97495747
 'NP' 5/8/21 2430pm
 c/s Resurvey after repair
 Tanjir @ Khumf-w
 6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: