

MTM AUTOMOTIQ PTE LTD

48 Toh Guan Road East #01-141 Enterprise Hub S(608586)
Tel: 6271 2088 ROC No. : 202107073H



ESTIMATE

TO : AXA INSURANCE
ATTENTION : MOTOR CLAIM DEPARTMENT

DATE : 4-Aug-2021
JOB TYPE : THIRD PARTY CLAIM

VEHICLE DETAILS

VEHICLE NO. : SMY7239Y
MAKE / MODEL : BMW 318I
CHASSIS NO. : WBA8E32050K497891
VEHICLE REG DATE : 11 Mar 2016

ACCIDENT DETAIL

DATE : ~~0-Jan-1900~~ 03/08/21
TIME : 2:10hrs 0:00

OWNER INSURANCE : NTUC INSURANCE

POLICY NO : 5122351567

ESTIMATOR : Donovan | HP: 97974474 | Donovan.leong@mtmperformancegroup.com

CLAIM DETAIL : LIST PRICE (S\$)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Front Bumper Repair Repair XR	1	\$1100 X	\$ -
2	Front Bumper Retainer LH X nn	1	\$48 X	\$ -
3	Front Grille X nn	1	\$220 X	\$ -
4	Headlamp LH CR / 3068	1	\$3205	\$ -
5	Front Support Panel X nn	1	\$110 X	\$ -
6	Front Reinforcement X nn	1	\$361.65 X	\$ -
7	Front Reinforcement cover X nn	1	\$52.15 X	\$ -
8	Front Headlight washer Assembly X nn	1	\$155.95 X	\$ -

3068
58
2914.60

TOTAL PRICE: \$5372.5-

LIST LESS 5%: \$268.6-

SUB TOTAL PRICE: \$5103.9-

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	DESCRIPTION	PRICE	ADJUST
1	Panel beating and renew of damage parts on affected area	\$ 560.00	250
2	Spray painting on affected area	\$ 560.00	250

} 500

3	Labor to calibrate of headlight to LTA standard	\$ 120.00	40
---	---	-----------	----

LABOUR TOTAL PRICE: \$ 1,240.00

540

ESTIMATE REPORT

TOTAL PARTS PRICE : #REF!
TOTAL LABOUR PRICE : \$ 1,240.00
TOTAL AMOUNT : #REF!

APPROVED DETAILS

NO.OF REPAIR DAYS : 3 days
P & P OR CUMPSUM :
SURVEYED BY : RASUL - Hp 90010068
CONTACT NUMBER : 90010068
E-MAIL :

Resy after repair

2914.60

540.00

3454.60

20%

2763.68

L/S - \$ 2,750

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: