



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 31944

Vehicle Insured : SKC 8000 B
Accident Date : 31-Jul-2021

Date : 03-Aug-2021

Our Ref : 021309 (AIG ASIA) / QUEK

PAGE : 1

TAY JOO SOON (MR)
Singapore

ESTIMATED COST OF REPAIR FOR AUDI A6 1.8 TFSI S TRONIC(2015) SCN928P =====

1 pc	front bumper		2,399.79
1 pc	RH front bumper side bracket		68.99
1 pc	RH front bumper side retainer		61.90
10 pcs	front bumper rivets	@ S\$ 10.00	100.00
1 pc	front bumper lower centre grille		200.00
1 pc	front bumper lower centre grille chrome moulding		388.60
1 pc	RH front bumper lower side grille		488.91
1 pc	front bumper towing cover		130.91
1 pc	front bumper centre bracket		133.71
1 pc	RH front bumper parking sensor - outer		249.79
1 pc	RH front bumper parking sensor - centre		249.79
2 pcs	front bumper parking sensor bracket - outer	@ S\$133.71	267.42
2 pcs	front bumper parking sensor bracket - centre	@ S\$133.71	267.42
1 pc	front bumper under cover		366.56
1 pc	front bumper reinforcement		1,009.79
1 pc	RH front bumper reinforcement bracket		460.71
1 pc	front bumper sponge		366.86
1 pc	front support panel		1,399.60
1 pc	front support panel top garnish		133.67
10 pcs	front support panel top garnish clips	@ S\$ 11.71	117.10

Con't Page 2 ...



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

Vehicle Insured : SKC 8000 B

Our Ref : 021309

Page : 2

No. : 31944

1 pc	RH headlamp panel	161.70	
1 pc	RH headlamp side bracket	169.97	
1 pc	front grille	1,777.71	
1 pc	RH front fender	955.00	
1 pc	RH front fender stone protection sticker	139.75	
1 pc	RH front fender inner bracket	167.71	
1 pc	RH front fender inner shield	185.50	
1 pc	RH front fender inner shield under cover	367.11	
1 pc	RH headlamp	8,840.00	
1 pc	RH headlamp nozzle pump	366.99	
1 pc	RH headlamp nozzle pump cover	133.71	
1 pc	RH headlamp nozzle pump hose	175.10	
1 pc	RH front rim	2,333.10	
1 pc	RH horn	233.91	

		24,868.78	
	Less 10% :	-2,486.88	

			22,381.90

1 pc	front number plate	40.00	sn
1 pc	RH front tyre	380.00	sn

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts. 800.00

To focus headlamps. To check front wiring and lighting operation. 50.00

To remove aircon condenser, pipes and driers. Vaccum and recharge gas 100.00

To conduct front wheel alignment test. 120.00

Con't Page 3 ...



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SKC 8000 B
Our Ref : 021309

Page : 3
No. : 31944

To putty and respray on affected
portions.

1,100.00

Total : S\$24,971.90

Singapore Dollars Twenty Four Thousand Nine Hundred
and Seventy One and Cents Ninety Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.