

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR JKK4127

No.	Qty	List Items	
1	1	Front windscreen glass	\$ RM 1,671.20 ✓
2	1 set	Front windscreen glass moulding	\$ RM 135.00 ✓
3	1	Roof panel assy 1115-76	\$ RM 3,500.20 ✓
4	1	Front LH windscreen pillar inner garnish/cover	\$ RM 178.00 X
5	1	Rear boot lid 1410.	\$ RM 1,540.20 ✓
			\$ 7,024.60
		Less 25%	\$ 1,756.15
		Total :	\$ 5,268.45
Special Nett Items			
6	1 set	Front windscreen sealant	\$ RM 50.00 4012
7	1 set	Front windscreen tinted film	\$ RM 150.00 12012
		Total :	\$ 200.00
Labour			
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 1,200.00 9001
2		To putty and spray Spray Paintings charges.	\$ 1,000.00 7501
3		To remove, refit front windscreen glass.	\$ 140.00 1201
4		To remove, refit roof lining and upholstery.	\$ 200.00 1201
5		To remove, refit cushion seats, including vacuum of broken glass.	\$ 100.00 501
6		To supply and apply anti rust treatment	\$ 80.00 801
		Total :	\$ 2,720.00
Total Parts and Labour :			\$ 8,188.45

Not Notional
 11 PM @ 4300h
 Penny After Rain
 9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: