

(08/11/13) wef

ASS. REC. BY: Jan

REF:

CS/CT121008248/R1gc

3202

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

SNM21D204313/C02

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLJ 686B

Yr Regn:

2016 / NOV

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezza 1.5X Hybrid c.c 1496

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

278889

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RU31210216

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/452R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

02/08/21

D.O.I.

18/08/21

Survey held at

KENT SENH

Des. of Damages: Frt / Rear / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair Int - 24K

20/08/21 @ 11.28am revised to Jenny Lew via Merimen.

02/09/21 @ 10.30am Rasul finalised with Kane LS \$2300, 6 days. (Red \$4449.50, 66%)

GIA REPORT IN VIEWS

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

6

1) 06/09 Typist

☐

: Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

) : \$ + RS, \$

☐

: Interview (\$

) : Photos

☐

: Tech. Invs (\$

) : Others

☐

: Weekend (\$

)

Report Format : MER-TP

Lump Sum ~~14.3K~~ (\$) 2300

TOTAL

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
Email:kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd DATE 18.08.2021
3 Anson Road #16-00 Spring leaf Tower CAR NO SLJ 686 B
Singapore 079909 MAKE Honda Vezel

ESTIMATED COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE
YOUR INSURED : SMQ 8898 E

Pc	Pcs		UNIT PRICE	AMOUNT
1	pc	Right side rocker panel moulding replaced repair		\$377.50
1	pc	Right side front door bt /		\$1,280.00
1	pc	Right side front door sticker (horizontal) re /		\$48.00
1	pc	Right side front door sticker (vertical) x		\$38.00
1	pc	Right side rear door bt /		\$1,030.00
1	pc	Right side rear door sticker (horizontal) re /		\$48.00
1	pc	Right side rear door sticker (vertical) re /		\$38.00
1	pc	Rear right side fender x		\$980.00
1	pc	Rear wheel arch garnish (right) replaced		\$195.00
8	pcs	Rear wheel arch garnish clips (right) x	\$5.00	\$40.00
1	pc	Rear wind screen moulding x		\$195.00
		Straightening, repairing and realigning on affected portion, dismantle & replace the above mentioned parts.		450 500 \$1,100.00
		To respray painting on all accident affected panels, right side front door, right side rear door, right side rocker panel and right side rear fender.	Resul 600	\$1,000.00
		Rust-proofing on the front accident affected.	Hp 900 600	\$120.00
		To apply silicon onto rear wind screen.	6 days	x \$80.00
		Labour for dismantle & refix rear wind screen.	43	x \$180.00
			18/08/21 P15W	
			Rey after repair	
			Page 1 of 1	Total \$6,749.50

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Susan Lim
KENT SENG CAR SERVICES.

Approved by Repairer

Signature

Date:

Survey Fee
Days of Repair
No. of Trip

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	370I
Vehicle No.:	SLJ686B
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Aug 2021
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X HYBRID A
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	LEB5910228
Chassis No.:	RU31210216
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$24,860.00
Original Registration Date:	28 Nov 2016
First Registration Date:	28 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2026
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	27 Nov 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$27,943.00
Total Rebate Amount:	\$31,693.00

The information contained herein is correct as at 19 Aug 2021

OK

Honda Vezel Hybrid 1.5A X

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$54,800

Depreciation 

\$10,280 /yr

[View models with similar depre](#)

Reg Date

20-Sep-2016

(5yrs 1mth COE left)

Mileage

68,000 km (13.8k /yr)

Manufactured 

2016

Road Tax 

\$682 /yr

Transmission

Auto

Dereg Value 

\$32,751 as of today ([change](#))

Fuel Type

Petrol-Electric

COE 

\$57,002

OMV 

\$24,430

Engine Cap

1,496 cc

ARF 

\$5,000

Curb Weight 

1,280 kg

Power

112.0 kW (150 bhp)

Type of Vehicle

SUV

No. of Owners 

1

Features