

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 20 Aug 2021

**Preliminary Advice**

Insured Vehicle No : SMQ8898E  
 TP Vehicle No : SLJ686B  
 Make : HONDA VEZEL  
 Date of Inspection : 18/08/2021  
 Inspection At : KENT SENG CAR SERVICES (YISHUN) (HQ)  
 BLK 1016 YISHUN INDUSTRIAL PARK A #01-238  
 SINGAPORE 768758

Accident Date : 02/08/2021  
 Assignment Date : 05/08/2021  
 Est. Duration of Repair : 6

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,749.50
Revised Amount	:S\$	3,604.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,604.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.