KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240 Singapore 768759 HP 91004390/HP 91254449 Fax 64841482

Email: kentsengcarservices@gmail.com

M/s	China Taiping Insurance (S) Pte Ltd	DATE	18.08.2021
	3 Anson Road #16-00 Spring leaf Tower	CAR NO	SLJ 686 B
	Singapore 079909	MAKE	Honda Vezel

-	IR IN	ED COST OF REPAIR FOR THE ABOVE MENTION SURED : SMQ 8898 E	UNIT PRICE	AMOUNT		
1 1	pc pc	Right side rocker panel moulding Right side front door by Right side front door sticker (horizontal)		\$377.50 XK \$1,280.00 980 \$48.00 \$38.00 X		
1 1 1 1 1	DC DC DC	Right side rear door sticker (vertical)	1713:20	\$1,030.00 \$48.00 \$38.00		
1 1 1 8 1	pc pc pc pcs pcs	Rear right side fender + ^^ Rear wheel arch garnish (right)		\$980.00 X \$195.00 X \$40.00 X \$195.00 X		
		Straightening, repairing and realigning on affe portion, dismantle & replace the above mention parts.	ned 4	\$1,100.00		
		To respray painting on all accident affected right side front door, right side rear door, riside rocker panel and right side rear fender Rust-proofing on the front accident affected To apply silicon onto rear wind screen. Labour for dismantle & refix rear wind screen	e front accident affected. The rear wind screen. The rear wind screen. The rear wind screen. The rear wind screen. The rear wind screen.			
		LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed	18/08/21 P1500 Rosy after 12	ruv		
			age 1 of 1 Total			
usan kolingged by Repairer		Louispartedged by Repairer	1715.	, , , ,		
NS	ENT SENT CAR SERVICES.		1100	w L/2-2,300		
		CAR SERVICES.	000	.20 -		
		CAR SERVICES.	2878	.20		
		CAR SERVICES.	2878	مر. ا		