

ASS. REC. BY: Tan JH

REF: CS/1A1G 21008249/Tinf3.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FK 311Z

at Workshop m/s BIKE PRODUCTION

of _____

Insured: _____

Policy No. 1900004396

Claims No. 6589432272SG

Sum Insured: _____ Excess: None

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$24K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Kwan. Vehicle: IN / OUT

Veh No: FK 311Z Yr Regn: 2019, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda ADV750 c.c. 745

Colour Silver A/C: Insured / Std / NI / NA

Sp. Reading 24729 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JH 2RC95 A.4KKZ008866

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 120/70R17

R: 160/60R15

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 5/8/21 0230pm

Survey held at Bike Production

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/8/2021 Revert to AIG via Merimen.

11/8/2021 @11.57am Thaddaeus informed C/A via Merimen.

11/8/2021 @1.15pm Informed Mr Kwan C/A & ex:\$750 via email.

Date/Time, File Pass to?

☐ : Preli. Report

1) _____
Date/Time, File Return to?

☐ : Final Report

2) _____

Report Format: _____

Lump Sum / L&A: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____ \$ + RS. _____ \$

Photos _____

Others _____

TOTAL _____

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 4 Aug 2021

ASSESSMENT FOR REPAIR: HONDA XADV750 - FK311Z

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$385.00 <i>cm</i>
1 pc	Front right fork assy	\$1,388.00 <i>SN4150</i> <i>X An</i>
1 pc	Steering stem	\$485.00 <i>?</i>
2 pcs	Steering stem bearing @ \$45.00	\$90.00 <i>?</i>
1 pc	Front wheel axle	\$188.00 <i>X</i>
1 pc	Front brake disk right	\$395.00 <i>?</i>
1 pc	Right rear side cover	\$450.00 <i>?</i>
1 pc	Right lower cover	\$375.00 <i>X</i>
1 pc	Front cover nose	\$199.00 <i>cm</i>
1 pc	Right side silver cover	\$185.00 <i>cm</i>
1 pc	Right side fairing assy upper	\$495.00 <i>cm</i>
1 pc	Right side fairing black cover	\$295.00 <i>cm</i>
1 pc	Right rear footrest	\$115.00 <i>mb</i>
1 set	Right side slider	\$235.00 <i>ant</i>
1 pc	Steering handle	\$305.00 <i>?</i>
1 pc	Right view mirror	\$145.00 <i>br</i>
1 pc	Right front signal assy	\$140.00 <i>ant</i>
1 pc	Right handguard	\$185.00 <i>ant</i>
1 pc	Right floorstep	\$305.00 <i>ant</i>
1 pc	Right skirt	\$295.00 <i>ant</i>
1 pc	Exhaust	\$1,105.00 <i>ant</i>
1 pc	Exhaust protector	\$198.00 <i>ad</i>
		\$5,610.00 7958
	Less discount 10%	\$561.00 795.8
		\$5,049.00 7162.20
	<u>Special nett items</u>	
1 pc	Front sport rim	\$885.00 <i>X</i>
1 pc	Rear number plate	\$35.00 <i>bt</i>
1 pc	Top case	\$215.00 <i>cut</i>
1)	Towing charges	\$120.00 <i>80</i>
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	<i>450</i> <i>300</i>
	To replace and balance front wheel	
3)	rim	\$150.00 <i>X</i>

- 4) To knock, straighten chassis & body balancing
- 5) To remove/refit, replace (if damage) check and straighten front fork tubes.
- 6) Spray painting

Total Estimate

200? photo
 \$380.00
 \$180.00 150 X nn
 \$300.00 200
 1.00

~~\$8,012.20~~

10,127.20

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd

Tanpin 97495749
 'WP' Ex: to be advise
 Resurvey new parts 5/8/21 @ 230pm
 Tanpin @ 11kauto.com
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: