

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 4 Aug 2021

ASSESSMENT FOR REPAIR: HONDA XADV750 - FK311Z

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$385.00
1 pc	Front right fork assy	\$1,388.00
1 pc	Steering stem	\$485.00
2 pcs	Steering stem bearing @ \$45.00	\$90.00
1 pc	Front wheel axle	\$188.00
1 pc	Front brake disk right	\$395.00
1 pc	Right rear side cover	\$450.00
1 pc	Right lower cover	\$375.00
1 pc	Front cover nose	\$199.00
1 pc	Right side silver cover	\$185.00
1 pc	Right side fairing assy upper	\$495.00
1 pc	Right side fairing black cover	\$295.00
1 pc	Right rear footrest	\$115.00
1 set	Right side slider	\$235.00
1 pc	Steering handle	\$305.00
1 pc	Right view mirror	\$145.00
1 pc	Right front signal assy	\$140.00
1 pc	Right handguard	\$185.00
1 pc	Right floorstep	\$305.00
1 pc	Right skirt	\$295.00
1 pc	Exhaust	\$1,105.00
1 pc	Exhaust protector	\$198.00
		<hr/>
		\$5,610.00
	Less discount 10%	\$561.00
		<hr/>
		\$5,049.00
	<u>Special nett items</u>	
1 pc	Front sport rim	\$885.00
1 pc	Rear number plate	\$35.00
1 pc	Top case	\$215.00
1)	Towing charges	\$120.00
	Replace, realign and adjust above damaged parts, check wiring and	
2)	lighting system	\$700.00
	To replace and balance front wheel	
3)	rim	\$150.00

4)	To knock, straighten chassis & body balancing	\$380.00
5)	To remove/refit, replace (if damage) check and straighten front fork tubes.	\$180.00
6)	Spray painting	\$300.00
Total Estimate		<u><u>\$8,014.00</u></u>

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd