

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 4 Aug 2021

ASSESSMENT FOR REPAIR: HONDA XADV750 - FK311Z

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$385.00 <i>cm</i>
1 pc	Front right fork assy	\$1,388.00 <i>SA 4150</i> <i>X An</i>
1 pc	Steering stem	\$485.00 <i>? X nn</i>
2 pcs	Steering stem bearing @ \$45.00	\$90.00 <i>? X nn</i>
1 pc	Front wheel axle	\$188.00 <i>X ✓ bent</i>
1 pc	Front brake disk right	\$395.00 <i>? bent</i>
1 pc	Right rear side cover	\$450.00 <i>? cracked</i>
1 pc	Right lower cover	\$375.00 <i>X</i>
1 pc	Front cover nose	\$199.00 <i>cm</i>
1 pc	Right side silver cover	\$185.00 <i>cm</i>
1 pc	Right side fairing assy upper	\$495.00 <i>cm</i>
1 pc	Right side fairing black cover	\$295.00 <i>cm</i>
1 pc	Right rear footrest	\$115.00 <i>mb</i>
1 set	Right side slider	\$235.00 <i>ant</i>
1 pc	Steering handle	\$305.00 <i>? bent</i>
1 pc	Right view mirror	\$145.00 <i>pin</i>
1 pc	Right front signal assy	\$140.00 <i>ant</i>
1 pc	Right handguard	\$185.00 <i>ant</i>
1 pc	Right floorstep	\$305.00 <i>ant</i>
1 pc	Right skirt	\$295.00 <i>ant</i>
1 pc	Exhaust	\$1,105.00 <i>ant ? bent</i>
1 pc	Exhaust protector	\$198.00 <i>ad</i>
	Less discount 10%	\$5,610.00 7958
		\$561.00 795.8
		\$5,049.00 7162.20
<u>Special nett items</u>		
1 pc	Front sport rim	\$885.00 <i>X</i>
1 pc	Rear number plate	\$35.00 <i>bt</i>
1 pc	Top case	\$215.00 <i>cut</i>
1)	Towing charges	\$120.00 <i>80</i>
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	<i>450</i> \$700.00 <i>300</i>
	To replace and balance front wheel	
3)	rim	\$150.00 <i>X</i>

- 4) To knock, straighten chassis & body balancing
- 5) To remove/refit, replace (if damage) check and straighten front fork tubes.
- 6) Spray painting

Total Estimate

200? photo
 \$380.00
 \$180.00 150 X nn
 \$300.00 200
 1.00

~~\$8,012.20~~

10,127.20

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd

Tanpin 97495749
 'WP' Ex: to be advise
 Resurvey new parts 5/8/21 @ 230pm
 Tanpin @ 11kauto.com
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: