

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	04 Aug 2021 13:34	Clm Veh Model Changed		[] Merimen Administrator
2	04 Aug 2021 13:34	Clm Created	Reg No: FK311Z. Policy No: 1900004396. Acct Date: 2021/08/01. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SC1K21830004	[I] Merimen Administrator
3	05 Aug 2021 10:14	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	05 Aug 2021 10:14	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	05 Aug 2021 10:14	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	05 Aug 2021 10:14	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/08/17	[A] LEE SU THING
7	05 Aug 2021 10:14	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] LEE SU THING
8	05 Aug 2021 10:14	Clm Registration Modified	Rep:1137->203419.	[A] LEE SU THING
9	05 Aug 2021 10:14	Clm Veh Model Changed	(206348) HONDA XADV750 745cc.	[A] LEE SU THING
10	05 Aug 2021 10:14	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] LEE SU THING
11	05 Aug 2021 13:04	Clm Registration Modified	Acct Time:17:30:00->17:00:00. Init.Est.:->5,000 - 6,000.	[I] Low, Xianyu
12	05 Aug 2021 14:28	Clm Registration Modified	Excess: -> 750.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
13	06 Aug 2021 10:29	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
14	06 Aug 2021 10:29	Clm Dtl Modified	JPJ Reg. Date: -> 2019/01/10.	[A] Elaine Kuan Hwa Meen
15	06 Aug 2021 10:29	Clm Details Notified		[A] Elaine Kuan Hwa Meen
16	06 Aug 2021 11:01	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/08/17	[A] Tan Hui Zhen
17	06 Aug 2021 11:03	Adj Mandate Request	Cur.Req:6886.30:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] Tan Hui Zhen
18	06 Aug 2021 13:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2021/08/17. Mandate Remarks: 1. Front right shock fork not subject for replacement require. 2. All fairing parts are raw material. Spray painting revised TBA	[I] Ng, Thaddaeus-HC
19	06 Aug 2021 13:02	Adj Mandate Set	Maintained:1. Front right shock fork not subject for replacement require. 2. All fairing parts are raw material. Spray painting revised TBA	[I] Ng, Thaddaeus-HC
20	11 Aug 2021 10:22	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2021/08/17	[A] Tan Hui Zhen
21	11 Aug 2021 10:23	Adj Mandate Request	Cur.Req:6666.30:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REP AIR.	[A] Tan Hui Zhen
22	11 Aug 2021 11:57	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2021/08/17. Mandate Remarks: 1. Front right shock fork not subject for replacement require. 2. All fairing parts are raw material. Spray painting revised TBA To arrange resurvey check, suppl and after repair photos	[I] Ng, Thaddaeus-HC
23	11 Aug 2021 11:57	Adj Mandate Set	Approved:6666.30:1. Front right shock fork not subject for replacement require. 2. All fairing parts are raw material. Spray painting revised TBA To arrange resurvey check, suppl and after repair photos	[I] Ng, Thaddaeus-HC

Date From    Date To    Audit Type 

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name	Ref 1	Ref 2	Amount
-------------	-----------	-----------	----------	----------	---------	-------	-------	--------

					(Branch)		
2714858	06 Aug 2021 10:29:56	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	FK311Z	11.00