

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0623/2021/KS
DATE : 2-Aug-21
WIP : 38047

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 04/08/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : M/S HELM ASIA PTE LTD
ADDRESS : 300 BEACH ROAD
#36-06, THE CONCOURSE
SINGAPORE 199555
TELEPHONE : HP +65 8294669
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 19001711992
VEHICLE NO : **SMQ 160 C**
MODEL CODE : AUDI A6 DEDIGN 2.0 TFSI
MODEL YEAR : 25/10/2019
ENGINE NO : DLH 065461
CHASSIS NO : WAUZZZF21LN014116
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Apr-21
PLACE OF ACCIDENT : 9 KENT RIDGE DR, SG 119241

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 160 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING LTD	S/N \$ 480.00	✓
2	TO DISMANTLE AND RENEW FRONT BUMPER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500
3	TO RESPRAY FRONT BUMPER.	\$ 1,000.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,872.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 160 C

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Rehnd</i>	1	\$ 2,832.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 650.00	+	
3	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	1	\$ 153.00	+	
4	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	1	\$ 210.00	+	
5	FRONT BUMPER SPOILER <i>new</i>	1	\$ 252.00	✓	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 434.00	+	
7	FRONT BUMPER AIR GUIDE - RH	1	\$ 29.00	+	
8	FRONT BUMPER AIR GUIDE - RH	1	\$ 21.00	+	
9	FRONT WHEEL HOUSING LINER - RH	1	\$ 266.00	+	
10	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - RH <i>new</i>	1	\$ 71.00	+	
11	FRONT WHEEL SPOILER - RH <i>Rehnd</i>	1	\$ 166.00	✓	
12	SUNDRIES ?		\$ 250.00	?	
TOTAL SPARE PARTS			: \$ 5,334.00		
TOTAL LABOUR CHARGES			: \$ 2,872.00		
GRAND TOTAL			: \$ 8,206.00		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *04/08/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *we authorised, 03 days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT