AIR ESTIMATE*

HICLE NO SHC1972C

*

DATE

MAKE

MODEL

: HYUNDAI IONIQ G3

CHIANG/CHINA

Unit Price

MODEL	·····onsinionia es		Onic Trio	
Qty	Parts Description/ Labour	Туре		Amount
	1 FRONT FENDER LH		l h	\$588.80
	1FRONT FENDER EMBLEM		ρ	\$26.60
	1FRONT BUMPER SIDE BRACKET LH			nn X \$35.00
	1LH SIDE ROCKER GARNISH		9	\$290.00
ia i	1 FRONT DOOR OUTER MOULDING LH		a	\$110.10
	1REAR DOOR OUTER MOULDING LH		ELL	\$125.30
4	1 LH WHEEL CAP FRT/REAR from LH + MA -	FHH	in (\$346.40)	\$692.80
ļ	SUB TOTAL		1192 20	\$1,868.60
	LESS 20%		1197.20	\$373.72
Δt	DISCOUNTED TOTAL]	957.76.	\$1,494.88
	1 REAR DOOR COMFORT APP STICKER		n	\$80.00
	1 FRONT DOOR COMFORT LOGO STICKER		_ 4	4 /\$75.00 /
			nee / 175	\$155.00
	July fach lid sticker (petrolonly)	\$20	nees	
	Labour Charge			
	Panel Beating		1525 n	\$700.00
	Spray Painting Charge		(000	\$1,100.00
	Remove/refix door parts		n	X \$60.00
	Check Wiring		1575	n x \$60.00
	TOTAL LABOUR	2		\$1,920.00
			1001	7-,3
	ESTIMATE TOTAL	ŀ	\$ 2657-76	\$3,569.88
	ESTIMATE TOTAL	1	W2 1.	73,303.00
	MA.	1	4 Joseph	1
This is an initial actionate based on a visual improcion of the above value. The first				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will			

Tanfhn 9749 749

Pp bonn befre punt

fanish & (Whanto-an

3 days

LK)

the

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and