

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

04/08/2021

ECICS LIMITED
7 Temasek Boulevard,
#10-01 Suntec Tower One,
Singapore 038987.

Attention :- ECICS

Page # :- 1

Veh # :- SKE1996M

Veh Model :- PROTON EXORA 1.6A

Estimate# :- CK422145

Claim # :-

ACC. Date :- 31/07/21

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT <i>bt</i>	1 PC	1,210.70	1,210.70 ✓
2.	REAR BOOT GARNISH <i>Xsu</i>	1 PC	396.50	396.50 X
3.	REAR BOOT LOGO <i>per</i>	1 PC	110.60	110.60 69
4.	REAR BOOT EMBLEM "EXORA" <i>per</i>	1 PC	120.00	120.00 45
5.	REAR BOOT EMBLEM "CPS" <i>per</i>	1 PC	96.30	96.30 55
6.	REAR BOOT LOCK <i>cub</i>	1 PC	117.00	117.00 ✓
7.	REAR BOOT CATCH <i>Xsu</i>	1 PC	65.00	65.00 X
8.	REAR BOOT RUBBER <i>per</i>	1 PC	176.80	176.80 123
9.	REAR WINDSCREEN MOULDING <i>Xnm</i>	1 PC	277.40	277.40 X
10.	REAR END PANEL <i>bt</i>	1 PC	699.00	699.00 520
11.	REAR END PANEL TRIM <i>de</i>	1 PC	277.60	277.60 189
12.	REAR BUMPER <i>de</i>	1 PC	965.10	965.10 630
13.	REAR BUMPER TOW COVER <i>Xsu</i>	1 PC	48.00	48.00 X
14.	REAR BUMPER REFLECTOR L+R <i>Xsu</i>	2 PC	79.00	158.00 X
15.	REAR BUMPER SPONGE - SVC	1 PC	220.10	220.10 X
16.	REAR BUMPER REINFORCEMENT <i>bt</i>	1 PC	479.20	479.20 325
17.	REAR BUMPER LOWER BRACKET L+R <i>2/1/2 H-Xsu</i>	2 PC	44.30	88.60 X
18.	REAR BUMPER RETAINER L+R <i>LH-2/1/2 H-Xsu</i>	1 PC	56.50	113.00 X
19.	REAR BUMPER CLIPS <i>per</i>	10 PC	4.40	44.00 ✓
20.	REAR FLOOR PANEL - TO REPAIR	1 PC		
21.	REAR CHASSIS MEMBER L+R - TO REPAIR	2 PC		
22.	REAR FENDER LH - TO REPAIR	1 PC		
LIST TOTAL S\$				5,662.90
10% DISCOUNT S\$				-566.29
				5,096.61
SPECIAL NET ITEMS :				
1.	REAR WINDSCREEN SEALANT <i>per</i>	1 PC	100.00	100.00 50
2.	REAR BUMPER SENSOR <i>per</i>	1 PC	280.00	280.00 200
3.	REAR NUMBER PLATE <i>cm</i>	1 PC	60.00	60.00 35
SPECIAL NET TOTAL S\$				440.00

LABOUR :

TO CUT & WELD REAR END PANEL, TO REPAIR REAR FLOOR PANEL, REAR FENDER L+R, REAR CHASSIS MEMBER. TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS

TO SPRAY REAR BOOT, BOOT GARNISH, REAR PANEL REAR FENDER PANEL, REAR BUMPER, REAR FENDER L+R AND AFFECTED AREAS

TO REMOVE & REFIX REAR WINDSCREEN GLASS

TO REMOVE & REFIX REAR BOOT MECHANISM CHECK & TEST WIPER MOTOR & CENTRE LOCKING SYSTEM

600 700.00

700 800.00

120 180.00

60 80.00

3327
108
2994+30

285

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

04/08/2021

ECICS LIMITED

7 Temasek Boulevard,
#10-01 Suntec Tower One,
Singapore 038987.

Attention :- ECICS

Page # :- 1 141666

Veh # :- SKE1996M

Veh Model :- PROTON EXORA 1.6A

Estimate# :- CK422145

Claim # :-

ACC. Date :- 31/07/21

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	TO REMOVE & REFIX LAGGAGE COMPARTMENT, SIDE GARISH, SIDE TRIM BOARD CARPET AND OTHER ATTACHMENT PARTS			60 80.00
	TO INSTALL REVERSE SENSOR & WATER TEXT	1740		60.00
	TO RUST PROOF AFFECTED AREAS			40 60.00
	LABOUR TOTAL S\$			1,960.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 7,496.61

GST @ 7 % 524.76

AMOUNT DUE S\$ 8,021.37

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

2994.30
285.00
1740.00
5019.30

20%
4015.44
4/5 - 4,000

7 days
=

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
7 days
4/5
16/08/21 P1155
Reg after repair