



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: PAY DANIEL			Ref: CS/ASM21008261/Bqce2 Date: 04/10/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHA 6233E	Veh. Inspected	SMF 8926R
	Policy No.		Coverage (\$)	0.00
	Claim No.	S1M03F2X	Excess (\$)	0.00
	Assign From	PAY DANIEL	Assign Date	05/08/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GP71213068	Colour	SILVER
	Odometer	292054 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	KAPSEN	6 mm
	L/H Front Tyre	185/60 R15	KAPSEN	6 mm
	R/H Rear Tyre	185/60 R15	KAPSEN	6 mm
	L/H Rear Tyre	185/60 R15	KAPSEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	05/08/2021	Inspection Date	10/08/2021
	Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	