

REPAIR ESTIMATE

Vehicle No. : SHC8411J

Make : HYUNDAI

Model : IONIQ(G3)

Date: 04/08/2021

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$430.90
10	FRT BUMPER CLIPS			\$22.00
1	FRT BUMPER SIDE BRACKER RH			\$28.00
1	RADIATOR GRILLE		X	\$1,409.10
1	FRT BUMPER MOULDING CENTRE UPPER		X	\$368.50
1	HEADLAMP RH		X	\$1,993.65
1	DAY LIGHT RH		X	\$642.50
1	FRT FENDER RH		bf	\$588.80
1	FRT FENDER SHEILD RH		fr	\$164.70
1	FRT WHEEL HUB CAP RH		ant	\$346.40
1	EMBLEM - BLUE DRIVE RH		rel	\$26.60
1	HEADLAMP SUPPORT PANEL		X	\$949.30
1	FRT DOOR MIRROR ASSY RH		Ry	\$1,391.70
	SUB TOTAL		1607-40	\$8,362.15
	LESS 20%			\$1,672.43
	DISCOUNTED TOTAL		1285-92	\$6,689.72
	Labour Charge			
	PANEL BEATING		525	\$1,050.00
	SPRAY PAINTING CHARGE		1055	\$700.00
	CHECK WIRING		30	\$60.00
	TOTAL LABOUR			\$1,810.00
	ESTIMATE TOTAL		2340-92 * 3 days	\$8,499.72

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tamphri 97495749
'wp' 4/8/21 @ 3pm
p/p Rising before peak
2-3 days
tamphri @ Phantoum

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: