

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK-

P1/2

DATE: 04/08/21

3P INSURANCE:

NTUC

CLF

MODEL: HYUNDAI I40

SURVEYOR:

LKK

VEH NO.: SHD3178K

MVA:

LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Bootlid	1		\$2,609.80 bc
	Bootlid Hinge (LH/RH)	2	\$142.30	284.60 bc
	Bootlid Lock Upper	1		\$114.90 X un
	Bootlid Lock Lower	1		\$31.70 bc
	Bootlid Hyundai Plate	1		\$21.10 un
	Bootlid 'H' Emblem	1		\$63.10 un
	Bootlid CRDI Plate	1		\$52.40 un
	Bootlid I40 Emblem	1		\$67.90 un
	Bootlid Lamp (LH/RH)	2	\$622.20 RH X	\$1,244.40 LH un
	Bootlid License Lamp	1		\$56.10 X un
	Bootlid Trimboard	1		\$343.90 X un
	Bootlid Moulding	1		\$85.00 de
	Bootlid Lower Outer Garnish	1		\$227.90 de
	Rear Bumper	1		\$1,106.00 de
	Rear Bumper Reinforcement	1		\$428.40 un
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00 un
	Rear Bumper Side Bracket RH/LH	2	\$80.30 RH X	\$160.60 LH un
	Rear Bumper Sponge	1		\$119.50 Gra
	Rear Bumper Under Cover	1		\$228.00 de
	Rear Bumper Reflector RH/LH	2	\$32.00 RH X	\$64.00 LH un
	Tail Lamp (LH/RH)	2	\$697.80 RH X	\$1,395.60 LH un
	Exhaust Muffler LH	1		\$967.70 X un
	Exhaust Pipe Centre	1		\$730.10 X un
	Rear End Panel	1		\$526.70 bc
	Rear End Lower Panel	1		\$495.50 Rx
	Rear End Panel Garnish	1		\$57.70 de
	Fuel Lid Cover	1		\$82.10 un
	Spare Wheel Panel	1		\$852.80 Rx
	Rear Wheel Cushion Cover	1		\$223.10 X un
	Rear Towing Hood	1		\$194.60 X un
SPARE PARTS SUB TOTAL			7446.20	\$12,857.20
LESS 20%			5956.96	\$2,571.44
DISCOUNTED SPARE PARTS TOTAL				\$10,285.76

NTWC L/S

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: