

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

6-Aug-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1447 Y

1 pc	Front bumper	✓ R/R	\$	811.11
1 pc	Front bumper emblem	X NN	\$	27.80
2 pcs	Front bumper n/s & o/s side bracket	\$32.51 RH-Gut/CHX NN	\$	65.02
1 pc	Front bumper o/s upper bracket	?	\$	92.60
1 pc	Front bumper o/s support bracket	?	\$	37.01
1 pc	Front bumper o/s fog light garnish	✓ S/R	\$	25.00
1 pc	Support panel	?	\$	1,292.20
1 pc	Front o/s head lamp	✓ L/R	\$	1,531.57
1 pc	Front o/s fender	✓ BUC.	\$	514.02
1 pc	Front o/s fender inner shield	✓ 2e.	\$	176.72
1 pc	Front o/s fender signal lamp	X	\$	32.10
1 pc	o/s mirror assy	X	\$	742.49
1 pc	Front o/s door quadrant moulding	X	\$	11.70
1 pc	Front o/s door	X repair	\$	1,723.60
2 pcs	Front o/s hinges @ \$36.10	X NN	\$	72.20
1 pc	Washer tank	?	\$	51.40
1 pc	Washer tank motor	?	\$	75.00
1 pc	Front o/s mud flap	X NN	\$	47.45
1 pc	Front o/s rim	✓ Cut	\$	246.00
1 pc	Front o/s lower arm	✓ BT	\$	811.34
1 pc	Front o/s shock absorber	?	\$	611.56
1 pc	Front o/s tie rod end	?	\$	72.50
1 pc	Front o/s ball joint	?	\$	91.90
1 pc	Front o/s knuckle arm	?	\$	873.88
1 pc	Front o/s knuckle bearing	✓ S/R	\$	349.60
1 pc	Front o/s stabilizer link	?	\$	88.50
				\$ 10,474.27
Less 20%				\$ 2,094.85
				\$ 8,379.42

S/NETT

1 set	Front bumper clips	✓	\$	48.00
1 pc	Front o/s fender sticker	✓	\$	30.00
1 set	Front o/s fender inner shield clips	✓	\$	28.00
1 set	o/s door stickers	✓	\$	100.00
1 pc	16' Tyre (Tyre Brand: Maxxis)	✓ S/R	\$	200.00

80.

Aug-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1447 Y

Sundry	\$	50.00	X 1 1 1
Towing Fee	\$	50.00	-
To check front o/s wheel alignment	\$	80.00	60
To adjust/focus front n/s & o/s head lamps	\$	80.00	20
To dismantle / refit the front o/s undercarriage	\$	250.00	200
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	X
To dismantle & refit the inner components of the front o/s door into the new shell door	\$	150.00	X } 1 1 1
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the o/s rocker panel, etc	\$	900.00	540
To putty and spray painting on front bumper, front o/s fender, front o/s door, front o/s windscreen pillar, o/s rocker panel, o/s side mirror	\$	1,200.00	540
To apply rustproofing on the repaired and replaced panels.	\$	150.00	50
	\$	<u>11,875.42</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

6 Days .
works on repair
After repair photos -
Gino Riccio
8288082
06/8/21

LUK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: