

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21008268/AGA3Q2**Date:** 06/04/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700078752
Claimant Vehicle No :	GBK4799X	Insured Vehicle No :	GBD5416G
Date of Loss:	02/08/2021	Nature of Claim:	TP
		Claim No:	9122644512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBK4799X		
Make & Model:	NISSAN NV200, 1.6 DX (A)	Engine No:	HR16161414D
Reg. Date:	30/07/2020 (Man. Year: 2019)	Chassis No:	VM20142489
Colour:	White	Odometer:	18481 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,494.39	3,600.91	3,893.48	51.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	1,120.00	1,910.00	63.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,524.39	4,720.91	5,803.48	55.14
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	10,524.39	3,750.00	6,774.39	64.37
+ GST 7.00/7.00% (S\$)	736.71	262.50	474.21	64.37
Nett Amount (S\$)	11,261.10	4,012.50	7,248.60	64.37
+ Loss of Use (7.0 x S\$85.00/day) (S\$)		595.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,614.95		
Global Sum Settlement (S\$)		4,580.00		

INSPECTION

Date of Assignment:	04/08/2021	MG Solution Pte Ltd (HQ)
Date Inspected:	04/08/2021 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,155.30 FL	*- FL
2	1		*TAILGATE NISSAN	Necessary	140.20 FL	*85.00 FL
3	1		*TAILGATE NV200	Necessary	90.00 FL	*90.00 FL
4	1		*TAILGATE VANETTE	Necessary	90.00 FL	*90.00 FL
5	1		*REAR BUMPER	Deformed	688.20 FL	*688.20 FL
6	2		*REAR BUMPER SIDE RETAINER	Not Necessary	124.80 FL	*- FL
7	1		*TAILLAMP	Cracked	320.50 FL	*320.50 FL
8	1		*TAILLAMP PANEL	Dented	180.20 FL	*180.20 FL
9	1		*REAR FENDER RH	Dented	2,355.20 FL	*1,798.00 FL
10	1		*REAR RAILWAY PANEL	Not Necessary	552.20 FL	*- FL
11	1		*REAR RAILWAY PANEL END	Cut	180.50 FL	*88.00 FL
12	1		*COMPANY ADVESTIMENT STICKER	Necessary	1,000.00 FS	*550.00 FS
13	1		*TAILGATE STICKER 70KM/H	Necessary	30.00 FS	*10.00 FS
14	1		*TAILGATE STICKER 6PAX	Necessary	30.00 FS	*10.00 FS
15	1		*SET REAR BUMPER CLIP	Necessary	25.00 FS	*25.00 FS
16	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
					Sub Total (S\$)	8,182.10 3,934.90
					- List Item Discount on L Items 10.00/10.00% (S\$)	687.71 333.99
					Total Parts (S\$)	7,494.39 3,600.91

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,400.00	600.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,200.00	400.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	80.00	30.00
5	TO REMOVE AND REFIX REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (\$)			3,030.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >