AUBURN AUTO PTE LTD

UEN: 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel: 8797 8998 Email: auburnauto.insurance@gmail.com

Vehicle Number : SLQ8769G (DOA 11.07.2021)

Make & Model : Hy

Elantra

Quantity	Description	Repairer's Estimate	
	BACK		/ BR
1	REVERSE SENSOR	300	
1	MISSING SCREWS & NUTS	\$250	/
1	RIGHT TAIL LIGHT BRACKET	\$120	X X 700 000
1	END PANEL GARNISH	\$250	\$ 111
1	TAIL LAMP LOWER BRACKET	\$120	
1	REAR RIGHT BUMPER RETAINER	\$250 45/	
1	REAR RIGHT TAILIGHT BRACKET	\$220	XXX
1	REAR LEFT TAILLIGHT BRACKET	\$220	X nn
1	REAR RIGHT DOOR BODY LINING	\$300	X nn
1	REAR RIGHT RIMS AND TYRE (LH)	\$500 450	CUT
1	REAR RIGHT WHEEL BEARING	\$200	X M
1	REAR LEFT WHEEL BEARING	\$200	- nec
1	REAR RIGHT DOOR BODY LINING	\$320	X NA
	SPARE TYRE BOARD	\$250	x nn
1	REAR CUSHION SEAT LOCK	\$200	X M
1	BOOTLID WEATHERSTRIP	\$180	- tru
1		\$550	X M
1	FAULTY WIRING	\$120	x R
1	REAR RIGHT BOOT MUDGUARD	\$ 1603	- 00
1	REAR LEFT BOOT MUDGUARD		X MA
1	BUMPER BRACKET	\$1,200	and the same of th
1	REAR RIGHT ABSORBER	\$750	/
1	REAR LEFT ABSORBER	\$750	X
1	REAR RIGHT MUDGUARD	\$120	TAI
1	REAR LEFT MUDGUARD	\$120	
1	LEFT BOOTLID LAMP	\$250 196	- CUIT
1	RIGHT BOOTLID LAMP	\$250 196	- CA!
1	LEFT TAIL LIGHT	4362	1 mis
1	RIGHT TAIL LIGHT	362	- CR
1	BOOT LOCK	\$150 \$ 116	- BT_
1	REAR UNDERCARRAIGE (Axic)	\$1,500 138	- BT
	BOOT LID	3927	1 00
1	SPARE TYRE WELL	\$250	XNO
1	BOOT INTERIOR LINING	\$500	x 120
1		\$2,000 486	1° BK
1	REAR BUMPER	\$2,000	tx R
11	END PANEL	\$2,000	1"
	SIDE		1 .
		\$150	30 -10
11	Bumper Clip Right	\$150	
1	Bumper Clip Left	\$200	X 10
1	Bumper Strip		1 nn
11	Front Right Rim	\$200	X
1	Rear Left Door Speaker	\$250	1xnn
1	Right Side Fender	\$250	XIO
1	Under Tray Cover	\$350	x nn
1	Rim tyre	\$360	
1	Right Headlight	\$400	_
1	Condenser	\$450	X
1	Radiator	\$450	1 x nn
1	Reinforcement Bar Sponge	\$450	X MI
1	Rear Left Door Replace	\$5,000 1476] - 00)
			·
	LABOUR & MISC		
	Tow	\$200 80	
1	Checking of wiring, lighting and resetting	\$300	730/
1	Remove and refit rear undercarriage	\$500	300
1		\$100	7 60/
1	Wheel alignment Remove and replace damaged parts	\$800	٦ẍ
1	Remove and replace damaged parts	· · · · · · · · · · · · · · · · · · ·	7
	Apply undercoating on repaired and	\$800	50/
1	replaced panel		7
	Workmanship to dismantle above damaged		1000
	parts, repairs including cut and wield,	4. 500	1000
1	realign body structure	\$1,500	
	Respray including polishing and waxing on		1
	the changed body parts, repaired		
	portortions where consistent to the	_	
1	accident	\$1,000	= 24%
1	accidents		1- 17/

Steve (LKK) 6/8/21, 19.90cm WIL PL L/S MAL Sy 14 dys

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8317 -20% P-6653-60 L-2420 9073-60 LIS-7258-88 =7250 Total loss