

SLH6189R

Vehicle Model : **HONDA SHUTTLE**
Accident Date : **05.08.2021**
Original Reg Date : **11.11.2016**

Chassis :
TP Ins.

GK81007711

INDIA

Asher.

ESTIMATE

1	1 pc	FRONT FENDER INNER COWLING RH <i>torn</i>		187.20	/
2	1 pc	FRONT FENDER RH <i>Dented</i>		645.20	/
3	2 pc	FRONT FENDER INNER PANEL RH <i>Buckled</i>		523.80	/
4	2 pc	FRONT FENDER INNER PANEL RH <i>Buckled</i>		752.30	x
5	1 pc	FRONT SIDESKIRT RH <i>new</i>		2,250.80	✓
6	1 pc	FRONT HEADLAMP RH <i>Cracked</i>		185.30	x.
7	1 pc	FRONT HEADLAMP LOWER BRACKET RH <i>new</i>		1,185.30	1050.
8	1 pc	FRONT BUMPER <i>Distorted</i>		95.20	45
9	1 pc	FRONT BUMPER SIDE RETAINER <i>Damaged</i>		82.90	42
10	1 pc	FRONT BUMPER TOW COVER <i>Missing</i>		698.30	297
11	1 pc	FRONT BUMPER REINFORCEMENT <i>Dented</i>		245.80	x.
12	1 pc	FRONT FOGLAMP RH <i>new</i>		125.90	/
13	1 pc	FRONT FOGLAMP COVER RH TOP <i>cracked</i>		135.80	/
14	1 pc	FRONT FOGLAMP COVER RH BOTTOM <i>cracked</i>		245.80	141
15	1 pc	FRONT LOWER GRILLE <i>Dented</i>		198.50	/
16	1 pc	FRONT BUMPER LOWER COVER <i>torn</i>		468.30	x
17	1 pc	FRONT RADIATOR GRILLE BASE <i>3rd</i>		398.20	x
18	1 pc	FRONT RADIATOR GRILLE CHROME <i>new</i>		782.90	x
19	1 pc	FRONT SUPPORT PANEL <i>new</i>		158.20	x.
20	1 pc	FRONT BONNET INNER LOCK BRACKET <i>new</i>		397.20	x
21	2 pc	FRONT RADIATOR AIR GUIDE <i>new</i>	198.60	397.20	x
22	1 pc	FRONT AIRCON PIPE <i>new</i>		245.80	x
23	1 pc	FRONT CONDENSER <i>new</i>		985.30	x
24	1 pc	FRONT WASHER TANK <i>cracked</i>		198.60	✓
25	1 pc	FRONT WASHER TANK MOTOR <i>new</i>		125.30	x.
26	1 pc	FRONT RH LOWER ARM <i>Best</i>		428.60	/
27	1 pc	FRONT RH SHOCK ABSORBER <i>Best</i>		485.20	✓
28	1 pc	FRONT RH KNUCKLE ARM <i>new</i>		582.30	x.
29	1 pc	FRONT WHEEL HUB BEARING RH <i>Damaged</i>		428.20	185
30	1 pc	FRONT TIE ROD RH <i>new</i>		185.60	x
31	1 pc	FRONT ANTI ROLL BAR LINKAGE RH <i>new</i>		152.80	x.
32	1 pc	FRONT ANTI ROLL BAR <i>new</i>		852.30	x.

14,432.90

Less 20%

2,886.58

total

11,546.32

6939.20

5551.36

Special Nett

1	1 SET	FRONT BUMPER CLIPS <i>Ne</i>		30.00	✓
2	1 SET	FRONT GRILLE CLIPS <i>Ne</i>		30.00	x
3	1 SET	FRONT FENDER INNER COWLING CLIPS <i>Ne</i>		30.00	✓
4	1 SET	FRONT TYRE RH <i>ct</i>		350.00	150.
5	1 SET	FRONT RIM RH <i>ct</i>		1,200.00	400.

580

Labour charge

PANEL BEAT / WELD AND REALIGN PARTS		1,800.00	800
SPRAY PAINTING		1,600.00	800.
ANTI RUST		120.00	80.
WIRING CHECK ON HEADLAMP /FOCUSSING		120.00	30
TO REMOVE /REPLACE FRONT UNDERCARRIAGE		280.00	200
COMPUTERISED WHEEL ALIGNMENT		120.00	80.
TOTAL		\$ 17,226.32	

1990

Adrian G

L/S . 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 8121.36

L/S: 6.5K

6.5K