

ASS. REC. BY:

REF:

TP / CS/TP21008281/Kuc

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: WBA7T22040CE38095

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN/OUT

Veh No:

38095

Yr Regn:

/

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

BMW

740Li

c.c

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading:

5880

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA7T22040CE38095

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☐ Nil / ☐ S/Rim / ☒ STD A/Rim or

Tyre Size:

F:

245/40R20

R:

275/35R20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

P

mm

D.O.A.

/ /

D.O.I.

30/7/2021

Survey held at

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

For LTA purpose, will contact Bryan for inspection after repair.
No repair days; no need Simon audit.

26/8/2021 Submit final fig \$3819. (RED \$330; 8%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 26/8 TYPIST

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS - SI

Fees

Others

TOTAL

135

50

13

80

278

Report Format: TP

Lump Sum / I.B.I: (\$ \$3819

leading the way...

Spare Parts

Submit By	:	<u>BRYAN TAN</u>
Year Manufacture	:	<u>2020</u>
Engine No.	:	<u>13045981</u>

Cost / List

Note: If any of the quoted parts are recommended to be repaired, will be charged accordingly under supplementary.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- ~~On additional labour charge~~
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:



Labour

Submit By : BRYAN TAN
Year of Manufacture 2020

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any

Vehicle no.: WBA7T22040CE38095

S/N.	PARTS		S/NETT		LABOUR
1	\$ 300.00				\$ 500.00
2	\$ 900.00				\$ 30.00
3	\$ 480.00				\$ 50.00
4	\$ 88.00				\$ 660.00
5	\$ 250.00				
6	\$ 80.00				
7	\$ 400.00				
8	\$ 81.00				
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
	\$ 2,579.00	\$ -	\$ -	\$ -	\$ 1,240.00
		Sub Total:	\$ 2,579.00	0%	
		0%	\$ -	\$ -	
			\$ 2,579.00	\$ -	
				TOTAL:	\$ 3,819.00
				0% Lump Sum:	\$ -
				Round Off:	\$ 3,819.00

CHECK:

S/N. PARTS

S/NETT

LABOUR

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

36

\$	-	\$	-	\$	-	\$	-	\$	-
		Sub Total:	\$	-		0%			
		0%	\$	-		\$	-		
			\$	-		\$	-		

TOTAL:	\$	-
0% Lump Sum:	\$	-
Round Off:	\$	-