

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008299/UPS3Q2
Date: 30/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800010817
Claimant Vehicle No :	SKW9336X	Insured Vehicle No :	SLW2670P
Date of Loss:	05/08/2021	Nature of Claim:	TP
		Claim No:	7714883971SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW9336X	Engine No:	10JBHD3011967
Make & Model:	CITROEN C4, 1.6 PICASSO (A)	Chassis No:	VF73ABHZTFJ746374
Reg. Date:	23/11/2015 (Man. Year: 2015)	Odometer:	114974 km
Colour:	Grey		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,082.12	5,808.82	7,273.30	55.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,500.00	1,870.00	2,630.00	58.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,582.12	7,678.82	9,903.30	56.33
Approved Total (Overridden) (S\$)		6,100.00		

Nett Amount (S\$)	17,582.12	6,100.00	11,482.12	65.31
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,936.45		
Global Sum Settlement (S\$)		6,900.00		

INSPECTION

Date of Assignment: 06/08/2021

Date Inspected: 06/08/2021

Estimated Period of Repair: 6.0 days

Inspected At: Zoom Autowerks Pte Ltd
832 SIMS AVENUE #12-884 EUNOSVILLE
Singapore 400832

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,519.00 FL	*1,215.00 FL
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	156.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	453.00 FL	*- FL
4	1		*SET REAR BUMPER REINFORCEMENT BEAM BOLT	Not Necessary	25.00 FL	*- FL
5	1		*REAR BUMPER GUIDE LH	Not Necessary	108.00 FL	*- FL
6	1		*REAR BUMPER GUIDE SECTION LH	Not Necessary	28.00 FL	*- FL
7	1		*REAR BUMPER BRACKET LH	Not Necessary	25.00 FL	*- FL
8	1		*REAR BUMPER SIDE REFLECTOR LH	Not Necessary	220.00 FL	*- FL
9	1		*REAR ULTRASOUND SENSOR LH	Not Necessary	415.00 FL	*- FL
10	1		*SET REAR ULTRASOUND SENSOR O-RING	Not Necessary	48.00 FL	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	68.00 FL	*50.00 FL
12	1		*TAILLAMP LED LH	Not Necessary	1,094.00 FL	*- FL
13	1		*REAR FENDER LH	Badly Dented / Bent	1,720.80 FL	*1,720.80 FL
14	1		*REAR FENDER INNER SHIELD LH	Torn	245.00 FL	*182.00 FL
15	1		*REAR FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*40.00 FL
16	1		*REAR FENDER QUARTER GLASS W/MOULDING	Not Necessary	1,586.00 FL	*- FL
17	1		*REAR FENDER AIR -VENT	Not Necessary	225.00 FL	*- FL
18	1		*REAR DOOR LH	Badly Dented	1,482.00 FL	*1,361.00 FL
19	1		*REAR DOOR INNER TRIM BOARD LH	Torn	956.00 FL	*956.00 FL
20	1		*REAR DOOR OUTER GLASS MOULDING LH	Not Necessary	286.00 FL	*- FL
21	1		*REAR DOOR INNER LOCK LH	Shorted	448.00 FL	*385.00 FL
22	1		*REAR DOOR LOWER HINGE LH	Not Necessary	128.00 FL	*- FL
23	1		*REAR DOOR TOP HINGE LH	Not Necessary	145.00 FL	*- FL
24	1		*REAR DOOR WEATHER STRIP LH	Not Necessary	386.70 FL	*- FL
25	1		*REAR FENDER (GLASS SEALANT N/S)	Necessary	80.00 FS	*40.00 FS
26	1		*REAR TYRE LH	Not Necessary	480.00 FS	*- FS
27	1		*REAR SPORTS RIM LH	Cut	1,286.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,673.50	6,399.80
- List Item Discount on L Items 5.00/10.00% (\$\$)	591.38	590.98
Total Parts (\$\$)	13,082.12	5,808.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REPAIR & RENEW LEFT AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
2	TO PUTTY ,SRPAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR LID COMPONENTS TRIM & GARNISH	New	150.00	0.00
5	TO REMOVE & INSTALL REAR SPARE TYRE COMPONENTS ,TRIM & GARNISH	New	150.00	0.00
6	TO REMOVE & INSTALL FENDER TRIM ,SEATS ,CARPETS ATTACHMENT TO FACILITATE REPAIRS	New	250.00	80.00
7	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	150.00	60.00
8	TO RE-PROGRAME & RESET DIAGNOSTIC SPEC	New	450.00	0.00
9	TO RE-POSITION DRILL & INSTALL REVERSE SENSOR	New	150.00	50.00
10	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
11	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (S\$)			4,500.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >