



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

Car Number: SKW9336X

Model : Citreon C4

Damaged Area: (Rear LH Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

not authorized
1/5 \$6100 6 days.
6/8/21

Parts / Material :

1	Rear Bumper	RE	1215.00	\$	1,519.00	✓
2	Rear Bumper Fixing Parts	11		\$	156.00	X
3	Rear Bumper Reinforcement Beam	11		\$	453.00	X
4	Rear Bumper Reinforcement Beam Bolt Set	11		\$	25.00	X
5	Rear Bumper Guide LH	11		\$	108.00	X
6	Rear Bumper Guide Section LH	11		\$	28.00	X
7	Rear Bumper Bracket LH	11		\$	25.00	X
8	Rear Bumper Side Reflector LH	11		\$	220.00	X
9	Rear Ultrasound Sensor LH	11		\$	415.00	X
10	Rear Ultrasound Sensor O-Ring (Set)	11		\$	48.00	X
11	Rear Bumper Clips (Set)	11	50	\$	68.00	✓
12	Taillamp LED LH	11		\$	1,094.00	X
13	Rear Fender LH	Body 20 / Surf		\$	1,720.80	✓
14	Rear Fender Inner Shield LH	Torn	182	\$	245.00	✓
15	Rear Fender Inner Shield Clips	11	40	\$	60.00	✓
16	Rear Fender Quarter Glass W/Moulding	11		\$	1,586.00	X
17	Rear Fender Air-vent	11		\$	225.00	X
18	Rear Door LH	Body 20	1361	\$	1,482.00	✓
19	Rear Door inner trim board LH	Torn		\$	956.00	✓
20	Rear Door Outer Glass Moulding LH	11		\$	286.00	X
21	Rear Door Inner Lock LH	shorted	385	\$	448.00	✓
22	Rear Door Top Hinge LH	11		\$	145.00	X
23	Rear Door Lower Hinge LH	11		\$	128.00	X
24	Rear Door Weather Strip LH	11		\$	386.70	X

Parts: \$ 11,827.50

Less Parts 5% : \$ 591.37

Total Parts : \$ 11,236.12

102

Special Net Items :

Rear Fender gloss sealant 115 180
Rear Tyre LH 11
Rear Sports Rim LH 11

\$ 80.00 40

\$ 480.00 X

\$ 1,286.00 450

Total S/N Parts : \$ 1,846.00

Labour :

To Remove, Repair & Renew Left Affected Accident Areas
To Putty, Spray Paint on Affected Accident Areas
To Check & Re-Connect all electrical wiring
To Remove & Install Rear Lid Components Trim & Garnish
To Remove & Install Rear Spare Tyre Components, Trim & Garnish
To Remove & Install Fender Trim, Seats, Carpets, Attachment to Facilitate Repairs
To Conduct Computerised Wheel Alignment
To Re-programme & Reset Diagnostic Spec
To Re-Position, Drill & Install Reverse Sensor
To Conduct Water Leakage Test
To Rust Proof Affected Areas

\$ 1,400.00 800

\$ 1,400.00 800

\$ 50.00 20

\$ 150.00 X

\$ 150.00 X

\$ 250.00 80

\$ 150.00 60

\$ 450.00 X

\$ 150.00 50

\$ 150.00 X

\$ 200.00 60

Total Labour : \$ 4,500.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5909.8
102
5318.82
490
1870
4678.82

TOTAL PARTS :	\$ 11,236.12
TOTAL SPECIAL NET ITEM :	\$ 1,846.00
TOTAL LABOUR :	\$ 4,500.00
TOTAL REPAIR COST :	<u>\$ 17,582.12</u>

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :