

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Aug 2021)
 Parts: M1-MPV HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Accord Auto Services Pte Ltd/SJG9064B/06/08/2021 14:29
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT WINDSCREEN X NN	0.00	0.00	*900.00 F
2	1		*FRONT WINDSCREEN MOULDING X NN	0.00	0.00	*40.00 F
3	1		*FRONT BONNET / OD	0.00	0.00	*450.00 F
4	1		*FRONT BONNET INSULATOR / CRV	0.00	0.00	*120.00 F
5	1		*FRONT BONNET LOCK ? / BT	0.00	0.00	*80.00 F
6	2		*FRONT BONNET HINGE / BT ?	0.00	0.00	*110.00 F
7	2		*FRONT BONNET STOPPER ? X NN	0.00	0.00	*16.00 F
8	1		*FRONT BONNET STAND ? X NN	0.00	0.00	*18.00 F
9	1		*FRONT BONNET STAND CLIP ? X NN	0.00	0.00	*5.00 F
10	1		*FRONT BONNET RUBBER/SEAL ? X NN	0.00	0.00	*80.00 F
11	1		*FRONT GRILLE BASE / BR	0.00	0.00	*130.00 F
12	1		*FRONT GRILLE CHROME / CRV	0.00	0.00	*160.00 F
13	1		*FRONT GRILLE LOGO / AL	0.00	0.00	*30.00 F
14	1		*FRONT LOWER GRILLE ? X NN	0.00	0.00	*80.00 F
15	1		*FRONT BUMPER / BR	0.00	0.00	*360.00 F
16	2		*FRONT BUMPER SIDE RETAINER / BR	0.00	0.00	*40.00 F
17	2		*FRONT BUMPER FOGLAMP GARNISH X NN	0.00	0.00	*170.00 F
18	1		*FRONT REINFORCEMENT BAR X NN	0.00	0.00	*180.00 F
19	1		*FRONT SUPPORT PANEL ? / DD	0.00	0.00	*320.00 F
20	1		*FRONT SUPPORT TOP COVER/GARNISH ? / BR	0.00	0.00	*85.00 F
21	1		*FRONT RH HEADLAMP / BR	0.00	0.00	*620.00 F
22	1		*FRONT RH HEADLAMP TOP PANEL X DD CC/w Support panel NN	0.00	0.00	*65.00 F
23	1		*FRONT RH HEADLAMP LOWER BRACKET / BR	0.00	0.00	*28.00 F
24	1		*FRONT RH FENDER / NN	0.00	0.00	*350.00 F
25	1		*FRONT RH FENDER SIGNAL LIGHT ? / BR	0.00	0.00	*28.00 F
26	1		*FRONT RH FENDER SHIELD ? X NN ? X NN	0.00	0.00	*70.00 F
27	1		*FRONT RH FENDER INNER PANEL TOP ? X NN	0.00	0.00	*500.00 F
28	1		*FRONT RH FENDER INNER PANEL CENTRE ? X NN	0.00	0.00	*320.00 F
29	1		*FRONT RH ABSORBER WHEEL HUB ? X NN	0.00	0.00	*580.00 F
30	1		*ENGINE MOUNTING SET ? X NN	0.00	0.00	*450.00 F
31	1		*WASHER TANK, NECK & CAP / CRV	0.00	0.00	*85.00 F
32	1		*AIRCON CPDENSER ? X NN	0.00	0.00	*520.00 F
33	1		*AIRCON CPDENSER DISCHARGE PIPE / BT	0.00	0.00	*280.00 F
34	1		*RADIATOR ? X NN	0.00	0.00	*600.00 F
35	2		*RADIATOR TOP STOPPER ? X NN	0.00	0.00	*20.00 F
36	1		*RADIATOR FAN COWLING ASSY ? X NN	0.00	0.00	*250.00 F
37	1		*RADIATOR TOP HOSE ? X NN	0.00	0.00	*90.00 F
38	2		*RADIATOR LOWER STOPPER ? X NN	0.00	0.00	*20.00 F
39	1		*RADIATOR LOWER STOPPER ALTERNATOR ? X NN	0.00	0.00	*400.00 F
40	1		*BELTING ? X NN	0.00	0.00	*60.00 F

F=Franchise part.

Sub Total (\$\$)	8,710.00
+ Margin on L,N Items 10.00% (\$\$)	871.00
Total Parts (\$\$)	9,581.00

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT BUMPER, FRONT BONNET INSULATOR, FRONT FENDER SHIELD & UNDER BUMPER/ENGINE COVER CLIPS <i>Rec 50-</i>	100.00
2	1	WINDSCREEN SEALANT <i>111</i>	40.00 X
Sub Total (\$\$)			140.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Spray Painting to All Affected Areas	New	1,200.00 <i>1000</i>
Labour Items			
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	New	1,000.00 <i>950</i>
3	Check Wiring System & Light	New	80.00 <i>30</i>
4	To Check & Adjust Wheel Aligment	New	80.00 X
5	To Remove/Refix Front Rh UnderCarriage To Facilities Repair	New	280.00 <i>100</i>
6	To Adjust Front Main Chassis	New	180.00 <i>120</i>
7	To Remove / Refix Air-con Condensor & Radiator (Top up Gas, Pipe & Etc...)	New	100.00 X
8	To Remove/Replace Windscreen	New	100.00
Gross Labour Cost (\$\$)			3,100.00

Accord Auto Services Pte Ltd/SJG9064B/06/08/2021 14:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Steve (LKK)
6/8/21, 4.09pm*

*OD-M M
EXCESS-?
L/S
M M M
8 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: