



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CS3/CTI21005362/T1f3n2-1 Date: 13/08/2021 Code: CTI	
1. Policy Particulars :- PAPER SURVEY			
Insured Veh.	GBD 8748D	Veh. Inspected	GBG 5142E
Policy No.	DMCVSNW00054952000	Coverage (\$)	0.00
Claim No.	SNM21D202494/C02	Excess (\$)	0.00
Assign From	ADELINE CHNG	Assign Date	06/08/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFHT02P300220258	Colour	GREEN
Odometer	146084 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/45 R18	TOURADOR	6 mm
L/H Front Tyre	225/45 R18	TOURADOR	6 mm
R/H Rear Tyre	225/45 R18	TOURADOR	6 mm
L/H Rear Tyre	225/45 R18	TOURADOR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/04/2021	Inspection Date	03/05/2021
Survey held at	QAS AUTO PTE LTD 3018A UBI ROAD 1 #01-23 SINGAPORE 408711		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	