

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SMZ 3444S

Vehicle Model : BMW 216I

Chassis Number : WBA2D920005E91641

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID / <i>bul</i>	1	\$ 2216.40 <i>1216.4</i>
2	BOOT LID LOCK <i>X NN</i>	1	\$ 195.75
3	BOOT LID WEATHERSTRIP <i>X NN</i>	1	\$ 144.55
4	"216 I" EMBLEM <i>- 1 MC</i>	1	\$ 126.75 <i>64.75</i>
5	BOOT LID LOGO <i>- 1 MC</i>	1	\$ 120.00 <i>60</i>
6	BOOT LID INNER TRIM BOARD <i>X NN</i>	1	\$ 568.10
7	BOOT LID INNER TRIM BOARD CLIPS <i>- MC</i>	10	\$ 50.00 <i>30</i>
8	BOOT LID SCREEN INNER SEAL <i>- MC</i>	1SET	\$ 150.00 <i>✓</i>
9	TAIL LAMP (LH & RH) <i>X NN</i>	2	\$ 1129.80
10	REAR BUMPER <i>- Re.</i>	1	\$ 1050.65 <i>✓</i>
11	REAR BUMPER CLIPS <i>- MC.</i>	10	\$ 50.00 <i>✓</i>
12	REAR BUMPER RETAINER (LH & RH) <i>X NN</i>	2	\$ 322.70
13	REAR BUMPER REFLECTOR (LH & RH) <i>BR</i>	2	\$ 156.20 <i>39.05</i>
14	REAR BUMPER CENTER CHROME MOULDING <i>RH X SVC</i>	1	\$ 210.55 <i>110.55</i>
15	REAR BUMPER REINFORCEMENT <i>BT</i>	1	\$ 483.40 <i>420.4</i>
16	TOWING CAP <i>X NN</i>	1	\$ 53.25
17	END PANEL <i>X Refr</i>	1	\$ 358.80
18	END PANEL UPPER GARNISH <i>X NN</i>	1	\$ 200.90
19	EXHAUST OUTER CHROME <i>- Cut</i>	1	\$ 213.85 <i>60</i>
20	EXHAUST INSULATION <i>BT</i>	1	\$ 154.60 <i>77.3</i>
21	SPARE TYRE TANK <i>X NN</i>	1	\$ 795.82
22	SPARE TYRE TANK UPPER BOARD <i>X NN</i>	1	\$ 339.67
23	REAR NUMBER PLATE LIGHT <i>X NN</i>	2	\$ 72.00
24	REVERSE CAMERA <i>X NN</i>	1	\$ 690.00

Bumper inner bracket (LH & RH) - \$322.30 *✓* *40* *BR*

Bumper inner bracket center - \$85.75 *✓* *Discount Less 10%*

List Prices Total \$ 8,868.37

S/N	Special Nett Items:	Qty	
1	REVERSE SENSOR <i>- DM</i>	1SET	\$ 1120.80 <i>766.3</i>
2	REAR NUMBER PLATE WITH HOLDER <i>- Set</i>	1SET	\$ 60.00 <i>40.</i>
Special Nett Total			\$ 1180.80
Spare Part's Total Price			\$ 10049.17

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SMZ 3444S

Vehicle Model : BMW 216I

Chassis Number : WBA2D920005E91641

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

S/N	Labour Descriptions	Charges
* 1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE	\$ 2000.00 400 800 600
2	TO SPRAY PAINTING ON: BOOT LID, REAR BUMPER, REAR BUMPER LOWER LIP, REAR END PANEL, SPARE TYRE TANK.	\$ 1800.00 400 600 700
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	\$ 150.00 40
4	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ X NN 280.00 250
5	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	\$ 150.00 60
6	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$ 150.00 730
7	LABOUR FOR REMOVE & INSTALL REAR SCREEN.	\$ 150.00 120
8	TO REMOVE & INSTALL BOOT COMPARTMENTS ATTACHMENTS, TRIMMINGS & FITTINGS TO ENABLE REPAIRS	\$ 150.00 60

4 Days -

Labour Total \$ 4830.00 1610

Parts & Labour Total \$ 14879.17

5525.66

-20%: 4400

Emp 9mm repair
After repair photos.
Gino Qian - 82880282
10/8/2021