

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SMZ 3444S

Vehicle Model : BMW 216I

Chassis Number : WBA2D920005E91641

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID / <i>but</i>	1	\$ 2216.40
2	BOOT LID LOCK <i>X NN</i>	1	\$ 195.75
3	BOOT LID WEATHERSTRIP ?	1	\$ 144.55
4	"216I" EMBLEM <i>- 5 acc</i>	1	\$ 126.75
5	BOOT LID LOGO <i>- 5 acc</i>	1	\$ 120.00
6	BOOT LID INNER TRIM BOARD <i>X NN</i>	1	\$ 568.10
7	BOOT LID INNER TRIM BOARD CLIPS <i>- acc</i>	10	\$ 50.00
8	BOOT LID SCREEN INNER SEAL <i>- acc</i>	1SET	\$ 150.00
9	TAIL LAMP (LH & RH) <i>X NN</i>	2	\$ 1129.80
10	REAR BUMPER <i>- acc</i>	1	\$ 1050.65
11	REAR BUMPER CLIPS <i>- acc</i>	10	\$ 50.00
12	REAR BUMPER RETAINER (LH & RH) <i>X NN</i>	2	\$ 322.70
13	REAR BUMPER REFLECTOR (LH & RH) <i>X NN</i>	2	\$ 156.20
14	REAR BUMPER CENTER CHROME MOULDING <i>- acc</i>	1	\$ 210.55
15	REAR BUMPER REINFORCEMENT ?	1	\$ 483.40
16	TOWING CAP <i>X NN</i>	1	\$ 53.25
17	END PANEL	1	\$ 358.80
18	END PANEL UPPER GARNISH ?	1	\$ 200.90
19	EXHAUST OUTER CHROME <i>- cat</i>	1	\$ 213.85
20	EXHAUST INSULATION ?	1	\$ 154.60
21	SPARE TYRE TANK <i>X NN</i>	1	\$ 795.82
22	SPARE TYRE TANK UPPER BOARD ?	1	\$ 339.67
23	REAR NUMBER PLATE LIGHT <i>X NN</i>	2	\$ 72.00
24	REVERSE CAMERA <i>X</i>	1	\$ 690.00

	\$ 9853.74
Discount Less 10%	\$ 985.37
List Prices Total	\$ 8,868.37

S/N	Special Nett Items:	Qty	
1	REVERSE SENSOR <i>- DM</i>	1SET	\$ 1120.80 ?
2	REAR NUMBER PLATE WITH HOLDER <i>- 2 - Sen</i>	1SET	\$ 60.00 40.

Special Nett Total \$ 1180.80

Spare Part's Total Price \$ 10049.17

ELITE AM PTE LTD

280 Woodlands Industrial Park

Harvest @ Woodlands Singapore

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SMZ 3444S

Vehicle Model : BMW 216I

Chassis Number : WBA2D920005E91641

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE	\$ 2000.00 <i>4000</i>
2	TO SPRAY PAINTING ON: BOOT LID, REAR BUMPER, REAR BUMPER LOWER LIP, REAR END PANEL, SPARE TYRE TANK.	\$ 1800.00 <i>400</i>
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	\$ 150.00 <i>40</i>
4	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ 280.00 <i>?</i>
5	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO BOOT LID & TEST FUNCTION	\$ 150.00 <i>60</i>
6	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$ 150.00 <i>?</i>
7	LABOUR FOR REMOVE & INSTALL REAR SCREEN.	\$ 150.00 <i>120</i>
8	TO REMOVE & INSTALL BOOT COMPARTMENTS ATTACHMENTS, TRIMMINGS & FITTINGS TO ENABLE REPAIRS	\$ 150.00 <i>60</i>

4 Days -

Imp from repair

After repair photos.

Gmo Qiang - 82880282

10/8/2021

Labour Total \$ 4830.00

Parts & Labour Total \$ 14879.17