

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Vehicle No.: SHD4054c
 Make : TOYOTA
 Model : PRIUS G4A
 DOA : 8/2/2021

Date :
 Insurance: CHINA
 MVA : CHIANG
 Admin :

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
				<i>ing</i> \$889.70
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			<i>ne</i> \$52.90
1	REAR TRUNK LID LOGO (PRIUS)			<i>ne</i> \$52.40
1	REAR TRUNK LID LOGO (HYBRID)			<i>ne</i> \$60.80
1	REAR TRUNK LID LOGO (TOYOTA STAR)			<i>de</i> \$458.60
1	REAR BUMPER			<i>de</i> \$552.60
1	REAR BUMPER UNDER COVER		\$112.70	? \$225.40
2	REAR BUMPER SIDE RETAINER LH/RH		\$2.20	<i>ne</i> \$22.00
10	REAR BUMPER CLIPS			<i>bt</i> \$318.80
1	REAR BUMPER REINFORCEMENT			? \$232.00
1	REAR BUMPER LOWER UNDER COVER			? \$223.00
1	REAR BUMPER UNDER SIDE COVER LH		<i>PMX</i> \$41.45	<i>LM?</i> \$82.90
1	REAR BUMPER REFLECTOR LH/RH			<i>de</i> \$82.70
1	REAR BUMPER TOWING COVER			<i>bt</i> \$1,126.60
1	REAR TRUNK LID COVER			<i>bt</i> \$457.90
1	REAR TRUNK LID LOCK			? \$165.80
1	REAR END PANEL GARNISH			<i>Ry</i> \$602.10
1	REAR END PANEL			<i>one</i> \$953.70
1	REAR SPOILER ASSY			<i>ant</i> \$557.90
1	TAIL LAMP UPPER LH			<i>ant</i> \$548.40
1	TAIL LAMP LOWER LH			<i>ant</i> \$65.30
1	BOOTLID LAMP TURN SIGNAL LH			<i>ne</i> \$1,778.30
1	TRUNK LID WINDSCREEN GLASS W/ MOULDING			<i>ne</i> \$1,569.70
1	REAR TRUNK LID GLASS BLACK			? \$312.00
1	SMART KEY ANTENNA			\$11,391.50
	SUB TOTAL			\$2,847.88
	LESS 25%			\$8,543.63
	DISCOUNTED TOTAL			
1	REAR NUMBER PLATE/WHOLDER			<i>bt</i> \$55.00
1	REAR TRUNK LID APPS STICKER			<i>ne</i> \$40.00
1	REAR TRUNK LID COMFORT & TEL NO. STICKER			<i>all</i> \$60.00
1	REAR BUMPER MAT			<i>ne</i> \$50.00
1	REAR WINDSCREEN GLASS SEALANT			<i>ne</i> \$43.00
1	REAR BUMPER REVERSE SENSOR			<i>ne</i> \$180.00
				\$428.00 NETT
	Labour Charge			
	Panel Beating			<i>700</i> \$1,200.00
	Spray Painting Charge			<i>750</i> \$1,000.00
	Wiring Charge			<i>30</i> \$60.00
	Diagnose and reset error code			<i>Report</i> <i>720</i> \$280.00

Part No.	Parts Description / Labour	Qty	Unit Price	Amount
	Towing Fee		<i>Towing receipt</i>	\$60.00
	Remove/Refix Reverse Sensor		<i>80</i>	\$60.00
	TOTAL LABOUR			\$2,660.00
	ESTIMATE TOTAL			\$11,631.63

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tamplin 97495747
up 4/8/21 @ 3pm
1/p Resurvey before period
3 days
Tamplin @ M&A auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 04.08.2021 10:45

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4105026

JC NO.: 305481381

MEMER

COMFORT TRANSPORTATION PTE LTD

7010045

MEMER NO.

383 SIN MING DRIVE

ESS

Singapore SINGAPORE 575717

65508755

(O)

(R)

(P)

DUNT CARD NO.

REGN NO.:

SHD4054C

MILEAGE

MAKE :

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4A02.08.2021 15:50

DATE/TIME IN

YR OF MANU

05.12.2019

TARGET DATE

CHASSIS CODE

JTDKB3FU103089204

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 02.08.2021
NATURE: 3P 02.08.2021

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

at:

to:

File No.:

SHD4054C

CHIANG

Exit Pass

Vehicle No.:

SHD4054C

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard