



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2107087

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 14/10/2021
Reference CC4/FCI21008315/Bra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMC 367Y

Insured Veh. SBS 3420C

Claim No. D21002190MFBP

Policy No. D-21097502MFBP

Accident Date 27/07/2021

Inspection Date 10/08/2021

Description	Total
Survey Inspection	210.00
Digital Photographs	
Transportation	
Subtotal	210.00
GST (7%)	14.70
Grand Total	224.70

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21008315/Bra3q2	
			Date: 14/10/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBS 3420C	Veh. Inspected	SMC 367Y
	Policy No.	D-21097502MFBP	Coverage (\$)	0.00
	Claim No.	D21002190MFBP	Excess (\$)	0.00
	Assign From	JACLYN	Assign Date	06/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GK81202071	Colour	BLACK
	Odometer	63788 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	175/65 R15	MICHELIN	6 mm
	L/H Front Tyre	175/65 R15	MICHELIN	6 mm
	R/H Rear Tyre	175/65 R15	MICHELIN	6 mm
	L/H Rear Tyre	175/65 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/07/2021	Inspection Date	10/08/2021
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 367Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR RH	NOT DAMAGED	1,632.40	-
1	FRONT DOOR BLACK TAPE RH	NOT NECESSARY	92.60	-
1	FRONT SIDE MIRROR RH	CUT	789.60	789.60
1	FRONT SIDE MIRROR COVER RH	CUT	241.00	130.00
1	FRONT SIDE MIRROR GLASS RH	NOT NECESSARY	198.00	-
	LESS 20% DISCOUNT		-590.72	-183.92
			2,362.88	735.68
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	FRONT DOOR SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT SIDE MIRROR SEAL (SN)	NECESSARY	60.00	30.00
1	FRONT SIDE GLASS SEALANT (SN)	NOT NECESSARY	100.00	-
			340.00	30.00
	<u>LABOUR</u>			
	R&R FRONT DOOR COMPONENT.	NOT NECESSARY	150.00	-
	CHECK WIRING .		100.00	20.00
	DIAGNOSTIC RESET FAULT CODE.	NOT NECESSARY	300.00	-
	PANEL BEATING.		800.00	200.00
	RUST PROOFING .	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		800.00	200.00
			2,350.00	420.00
	GRAND TOTAL		5,052.88	1,185.68
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			950.00

Report Ref No. CC4/FCI21008315/Bra3q2

LIM TEOW GUAN

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 367Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

