

ASS. REC. BY:

Stere

REF

ASSIGNMENT

From:

Date:

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report

Consistent? : Yes or No

SIA / PR Seant

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKW 315R

Yr Regn:

1

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

C.C.

1496

Colour:

White

A/C:

Insured / Std / NI / N

Sp. Reading

86297

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

P11132297

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fire 29

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

U/Bal.

4

mm

U/Bal.

4

mm

D.O.A.

27/7/21

D.O.L.

6/8/21

Survey held at

Cycle & Carriage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

No PAFF Value

Date/Time, File, Post to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS \$

Phone

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (%)



: Weekend (\$

Approved by:

Signature / Date

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address

Owner Name & Vehicle Info

CHAN'S & SONS ENTERPRISE

363 SEMBAWANG ROAD
GOODLINK PARK
SINGAPORE 758379

Contact No

Reg No/Reg Date SKW315R / 14/10/2015
Date In/Mileage / 0
Chassis No RU11102297
Engine No L1584022298
Make/Model Vezel 1.5X CVT

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00061	Cash	06/08/2021/ 12:18	TLC	442 / CocoLu	26478

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, TAILGATE, REPAIR REAR END PANEL, REAR BUMPER LH 200 X 2		470		1050.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER LH, REAR END PANEL, TAILGATE, 200 X 2		470		1120.00
E PNT88000 REMOVE & INSTALL TAILGATE GLASS		120		200.00
M SUNDRY APPLY SEALANT FOR TAILGATE GLASS		40		80.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION		20		40.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM		30		160.00
M SUNDRY Sundry				20.00
M SUNDRY REAR BUMPER / DD		508		860.00
M SUNDRY TAILGATE / DD		1050		1537.00
M SUNDRY TAILGATE GLASS MOULDING 45 X 4 / n/c		180		260.00
M SUNDRY EMBLEM / n/c				45.00
M SUNDRY REAR BUMPER SIDE BRACKET X nn				37.00

Estimate

Steve (LKK) with PL
6/8/21, 2:30pm L/S
My AL sy
4 days

LKK Auto Consultants hence notify the Repairer of the following:

Confirm & accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

7% GST on **Nett** 5,409.00
378.63
Total Payable 5,787.63

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4558 Fax: (65) 6567 5258