



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHAN'S & SONS ENTERPRISE 363 SEMBAWANG ROAD GOODLINK PARK SINGAPORE 758379 Contact No	Reg No/Reg Date SKW315R / 14/10/2015 Date In/Mileage / 0 Chassis No RU11102297 Engine No L15B4022298 Make/Model Vezel 1.5X CVT

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00061	Cash	06/08/2021/ 12:18	TLC	442 / CocoLu	26478

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, TAILGATE , REPAIR REAR END PANEL, REAR BUMPER LH				1050.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER LH, REAR END PANEL, TAILGATE,				1120.00
E PNT88000 REMOVE & INSTALL TAILGATE GLASS				200.00
M SUNDRY APPLY SEALANT FOR TAILGATE GLASS				80.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				160.00
M SUNDRY Sundry				20.00
M SUNDRY REAR BUMPER				860.00
M SUNDRY TAILGATE				1537.00
M SUNDRY TAILGATE GLASS MOULDING \$65 X 4				260.00
M SUNDRY EMBLEM				45.00
M SUNDRY REAR BUMPER SIDE BRACKET				37.00

Confirm & accepted by

7% GST on **Nett** 5,409.00
5409.00 378.63

Authorized signatory and company stamp

Total Payable 5,787.63

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

DPS Auto Services

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4558 Fax: (65) 6567 5258