

ASS. REC. BY:

REF:

TE / 21008319/KC
CAB

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02 days

Res.: Yes or No

Lum Sum: _____

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 Got BT, Battery flat

1218 & 2175.28 Carhu

Veh No: _____

SHD 98755

Yr Regn: _____

11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toy Prow

c.c.

1798

Colour: _____

White

A/C: _____

Insured / Std / Nil / NA

Sp. Reading: _____

T/Radio: _____

Insured / Std / Nil / NA

Eng/No: _____

C/No: _____

JTDKB3FU203092810

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size: _____

F: Daim

195/65R15

R: Dm

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. _____

9

mm

R/Bal. _____

4

mm

L/Bal. _____

9

mm

L/Bal. _____

4

mm

D.O.A. _____

4/8/21

D.O.I. _____

11/8/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S 157

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

: P. 155

: Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD98755

Not Authorized
Repair B4 paint
\$ 2175.28

AAD2108-

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD98755

JTDKB3FU203092810

TOYOTA

PRIUS GEN 4

04/08/2021

IX

20/11/2020

11 AUG 2021**PART**

- 1 COVER, FRONT BUMPER
- 1 MOULDING, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 LINER, FRONT FENDER, LH

LIST

\$	<i>Bul / Dca</i>	521.00	✓
\$	<i>Gr</i>	95.60	✓
\$	<i>D17</i>	59.30	✓
\$	<i>R1</i>	977.80	✓
\$	<i>Ln</i>	210.30	X
TOTAL \$		1,864.00	
25% \$		466.00	
\$		1,398.00	

Special Nett

- 1SET FRONT BUMPER CLIP
- 1 FENDER CLIP
- 1 FENDER LINER CLIP

\$	<i>nn</i>	90.00	<i>Scsn</i>
\$	<i>nn</i>	60.00	X
\$	<i>nn</i>	60.00	X
TOTAL \$		90.00	

TOTAL PARTS \$ 1,488.00**LABOUR**

Panel Beating, Knocking And Straightening The Necessary Portion,
Remove And Renewal Of Parts, Adjust And Realign The Same
To remove and refit interior fittings, trimings, garnish, fittings and
other, to enable repair.

\$ 1,600.00 *4001*
\$ *nn* 380.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *301*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

Trans-cab Auto Services Pte Ltd

AAD2108-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD98755

Putty And Spray Painting Of The Affected Portion. \$ 1,600.00 ⁴⁴⁰¹To transfer of tire, rim and on wheel balancing. \$ 170.00 ⁿⁿ XTo Check Electrical Lighting Concerned. \$ 170.00 ^{15/}**TOTAL \$ 4,380.00****Over All Total \$ 5,868.00****(PART-BY-PART) Repair Days 20 days**^{2 days}**LKK Auto Consultants** hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD98755
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Aug 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS SDR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2H22557
Chassis No.:	JTDKB3FU203092810
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	20 Nov 2020
First Registration Date:	20 Nov 2020
Transfer Count:	0
Actual ARF Paid:	\$14,530.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2028
PARF Rebate Amount:	\$10,897.00
Intended COE Rebate Details	
COE Expiry Date:	19 Nov 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$29,180.00
COE Rebate Amount:	\$23,344.00
Total Rebate Amount:	\$34,241.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Aug 2021

OK