

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5931U***Not Withheld  
\$ 500/h***AAD2108-**

Vehicle No.:  
 Chassis No.:  
 Vehicle Make: **05 AUG 2021**  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration :

**SHC5931U**

VF1ABL15AUC281484

RENAULT

LATITUDE

04/08/2021

AIG.

06/03/2015

<b>PART</b>	<b>LIST</b>
1 BUMPER COVER FRT	\$ <i>11</i> 747.20 X
1 BUMPER ABSORBER FRT	\$ <i>12</i> 394.68 X
1 BUMPER BEAM FRT	\$ <i>11</i> 663.70 X
1 BUMPER BRACKET KIT FRT RH	\$ <i>12</i> 101.40 X
1 HEADLAMP RH	\$ <i>12</i> 743.60 X
1 WIPER RESERVOIR	\$ <i>12</i> 179.60 X
1 FENDER PANEL FRT RH	\$ <i>11</i> 437.10 X
1 WHEELARCH FRT RH	\$ <i>12</i> 191.40 X
	<b>\$ 3,267.28</b>
	<b>10% \$ 326.73</b>
	<b>\$ 2,940.55</b>

<b>Special Nett</b>	
1SET BUMPER BRACKET CTR CLIP	\$ <i>11</i> 33.00
1SET BUMPER BRACKET SIDE CLIP RH RR	\$ <i>11</i> 10.00
1SET BUMPER RETAINER RH CLIP RR	\$ <i>11</i> 20.00
1SET BUMPER BRACKET SIDE CLIP LH RR	\$ <i>11</i> 10.00
1SET BUMPER RETAINER CLIP LH RR	\$ <i>11</i> 20.00
1 BUMPER CLIP FRT	\$ <i>11</i> 85.00
1 FENDER CLIP	\$ <i>11</i> 65.00
1 FENDER LINER CLIP	\$ <i>11</i> 60.00
<b>TOTAL</b>	<b>\$ 303.00</b>
<b>TOTAL PARTS</b>	<b>\$ 3,243.55</b>

**LABOUR**

Putty And Spray Painting Of The Affected Portion. \$ 3,000.00 *4401*

**Trans-cab Auto Services Pte Ltd**

AAD2108-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5931U

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X

**TOTAL \$ 7,580.00****Over All Total \$ 13,764.10****(LUMP SUM)****Repair Days****10 DAYS****1 day****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer****Signature:****Date:**