

ASS. REC. BY:

REF:

AIG/210083201K6

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or NoLum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: PHC 59314 Yr Regn: 03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AMake: Perant Latitude c.c. 1995Colour M. White/Red A/C: Insured / Std / NI / NASp. Reading 706878 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIABZ15AUC 281484Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pailon

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 4/8/21 D.O.I. 5/8/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 PM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 GIA not ready, may have BZ8500h Cab

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$)

☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5931U*Not Withheld*
*\$ 5000***AAD2108-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

05 AUG 2021**SHC5931U**

VF1ABL15AUC281484

RENAULT

LATITUDE

04/08/2021

AIG.

06/03/2015

PART

- 1 BUMPER COVER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER BEAM FRT
- 1 BUMPER BRACKET KIT FRT RH
- 1 HEADLAMP RH
- 1 WIPER RESERVOIR
- 1 FENDER PANEL FRT RH
- 1 WHEELARCH FRT RH

LIST

\$	<i>n</i>	747.20	X
\$	<i>Sh</i>	394.68	X
\$	<i>n</i>	663.70	X
\$	<i>Sh</i>	101.40	X
\$	<i>Sh</i>	743.60	X
\$	<i>Sh</i>	179.60	X
\$	<i>n</i>	437.10	X
\$	<i>Sh</i>	191.40	X
\$		3,267.28	
10% \$		326.73	
\$		2,940.55	

Special Nett

- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1 BUMPER CLIP FRT
- 1 FENDER CLIP
- 1 FENDER LINER CLIP

\$	<i>nn</i>	33.00	}	<i>X</i>
\$	<i>h</i>	10.00		
\$	<i>h</i>	20.00		
\$	<i>h</i>	10.00		
\$	<i>h</i>	20.00		
\$	<i>h</i>	85.00		
\$	<i>h</i>	65.00		
\$	<i>h</i>	60.00		
TOTAL \$		303.00		
TOTAL PARTS \$		3,243.55		

LABOUR

Putty And Spray Painting Of The Affected Portion.

\$

3,000.00

4401

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5931U**AAD2108-**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	601
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X

TOTAL \$ 7,580.00**Over All Total \$ 13,764.10****(LUMP SUM)****Repair Days****10 DAYS****1 day****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5931U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	05 Aug 2021
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002616
Chassis No.:	VF1ABL15AUC281484
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	06 Mar 2015
First Registration Date:	06 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Mar 2023
PARF Rebate Amount:	\$8,123.00
Intended COE Rebate Details	
COE Expiry Date:	05 Mar 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,092.00
COE Rebate Amount:	\$10,111.00
Total Rebate Amount:	\$18,234.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Aug 2021

OK