

Date: 6 August 2021

REPAIR DETAILS		
REFERENCE		
Vehicle Reg. No.	GBK7198K	
Make & Model	TOYOTA / DYNA 150 5MT	
Chassis No.	JTFAT35Y50K215767	
Engine No.	1KDB050831	
Manufacture Year	2020	
TP Vehicle Reg. No.	SHB976D	
DOA & Location	04/08/2021	SLIP ROAD TOWARDS KJE FROM CHOA CHU KANG WAY

ESTIMATES OF PARTS

No.	Description	Qty	Price
1	REAR END PANEL	1	\$ 1,399.70
2	TAILLAMP BRACKET RH	1	\$ 258.60
3	TAILLAMP BRACKET LH	1	\$ 258.60
4	TAILLAMP ASSY RH	1	\$ 245.60
5	TAILLAMP ASSY LH	1	\$ 245.60
6	EXHAUST ASSY	1	\$ 1,856.20
7	NO PLATE BRACKET	1	\$ 250.40
8	REAR CHASSIS LH	1	\$ 958.50
9	REAR PARKING SENSOR	2	\$ 640.00
		Sub-Total (S\$)	\$ 6,113.20
		SAAA List Item Discount 25% (S\$)	\$ 1,528.30
		Total Parts (S\$)	\$ 4,584.90

LABOUR

No.	Description	Price	
1	LABOUR	\$	800.00
2	SPRAYPAINTING	\$	800.00
3	ANTI-RUST COATING AND APPLY CORROSION PROTECTION	\$	200.00
Total Labour (S\$)		\$	1,800.00

MISCELLANEOUS ITEMS

No.	Description	Price
1	NUMBER PLATE	\$ 40.00
2	REAR STEP PANEL ASSY	\$ 1,500.00
Total Miscellaneous Items (S\$)		\$ 1,540.00

	Total Parts (S\$)	\$	4,584.90
	Total Labour (S\$)	\$	1,800.00
	Total Miscellaneous (S\$)	\$	1,540.00
	Total (S\$)	\$	7,924.90
	GST 7% (S\$)	\$	554.74
	Grand Total (S\$)	\$	8,479.64