



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21008326/Euf3n2	
			Date: 24/08/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 976D	Veh. Inspected	GBK 7198K
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/08/21/2006	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	10/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	JTFAT35Y50K215767	Colour	WHITE
	Odometer	31316 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	155/70 R15	DUNLOP	4 mm
	L/H Front Tyre	155/70 R15	DUNLOP	4 mm
	R/H Rear Tyre	155/70 R15	DUNLOP	4 mm
	L/H Rear Tyre	155/70 R15	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/08/2021	Inspection Date	10/08/2021
	Survey held at	CHENG AUTO BODYWORKS 1 SOON LEE STREET #06-41 PIONEER CENTRE SINGAPORE 627605		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	