



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200175

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 07/01/2022
Reference CC6/CTI21008335/Kea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMZ 5812A
Insured Veh. GBH 4563A
Claim No. SNM21D204396/C02
Policy No. DMCVSNW00054982103
Accident Date 08/08/2021
Inspection Date 10/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI21008335/Kea3q2 Date: 07/01/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 4563A	Veh. Inspected	SMZ 5812A	
Policy No.	DMCVSNW00054982103	Coverage (\$)	0.00	
Claim No.	SNM21D204396/C02	Excess (\$)	0.00	
Assign From		Assign Date	10/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	RU11332580	Colour	METALLIC GREY	
Odometer	15199 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	8 mm	
L/H Front Tyre	215/60 R16	DUNLOP	8 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/08/2021	Inspection Date	10/08/2021	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 5812A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	1,210.90	953.00
1	REAR TAILGATE 'VEZEL' EMBLE	NECESSARY	55.10	55.10
1	REAR TAILGATE 'HONDA' LOGO	NECESSARY	58.50	58.50
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	181.00	181.00
1	REAR TAILGATE LH REFLECTOR	CRACKED	381.50	381.50
1	REAR TAILGATE OUTER GARNISH	MTG CRACKED	485.50	485.50
1	REAR TAILGATE OUTER GARNISH CHROME	NECESSARY	181.50	181.50
1	REAR TAILGATE INNER LOCK	TO REPAIR SEE LABOUR	198.40	-
1	REAR TAILGATE INNER RUBBER	SERVICEABLE	135.20	-
1	REAR TAILGATE INNER GARNISH	MTG DISTORTED	420.50	420.50
1	REAR LH TAILLAMP	CRACKED	485.50	485.50
1	REAR LH SIDE BUMPER	BUCKLED	385.20	385.20
1	REAR BUMPER	BENT	986.30	689.00
2	REAR BUMPER SIDE RETAINER @\$24.80	N/S DISTORTED	49.60	24.80
1	REAR BUMPER LH REFLECTOR	CRACKED	85.20	85.20
1	REAR END PANEL	BENT	580.90	580.90
1	REAR END PANEL INNER GARNISH	MTG DISTORTED	250.20	188.00
1	REAR END PANEL OUTER SENSOR	SERVICEABLE	195.25	-
1	REAR LH FENDER PROTECTOR	BUCKLED	195.20	195.20
1	TAILLAMP PANEL LH	BENT	350.00	350.00
	LESS 20% DISCOUNT		-1,374.29	-1,140.08
			5,497.16	4,560.32
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR NUMBER PLATE & CASING (SN)	SERVICEABLE	50.00	-
1	SEALANT (SN)	NECESSARY	80.00	40.00
			410.00	240.00
<u>LABOUR</u>				
	REMOVE & REFIX REAR WINDSCREEN GLASS .		120.00	120.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIRING .		80.00	20.00
	TUFFKOTE.		80.00	60.00
	SPRAY PAINTING.		1,000.00	800.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR TAILGATE INNER LOCK .		1,000.00	600.00
			2,280.00	1,600.00
GRAND TOTAL			8,187.16	6,400.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,100.00

Report Ref No. CC6/CTI21008335/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 5812A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 5812A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 5812A

RE-INSPECTION

