

(08/11/13) wef

A.C.S. REC. BY: Marcus

REF:

CS/AG/21008337/4v3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

432 i

Date / Time

Action / Instruction

LTA 36491

Rep 11k.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )

Veh No: SM28088D

Yr Regn: 31/10/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or AI

Make:

BMW 116D c.c. 1496

Colour:

silver

A/C: Insured / Std / NI / NA

Sp. Reading

73829

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA1V720705G87184

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/35 R19 P.r

R: 255/30 ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

06/08/21

D.O.I.

10/8/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

17/8/21 d/s £4500 confirmed with Eilin

Submit to insurance



## ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SMZ8088D

Model : BMW

Damaged Area: (Rear RH Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

not Authorised  
due  
10/8/11  
2/5 & 4500  
sday

### Parts / Material :

1	Rear Bumper	2	\$ 1,087.40	X
2	Rear Bumper Bracket RH	1	\$ 176.40	X
3	Rear Bumper Side Retainer RH	1	\$ 116.20	X
4	Rear Bumper Reflector RH	1	\$ 158.60	X
5	Reverse Sensor Bracket (Set)	1	\$ 96.00	X
6	Rear Bumper Clips (Set)	1	\$ 60.00	X
7	Rear Taillamps RH	1	\$ 786.50	X
8	Rear Fender RH	10/warped	\$ 1,295.80	X
9	Rear Fender Inner Shield RH	1	\$ 286.40	X
10	Rear Fender Inner Shield Clips (Set)	1	\$ 60.00	X
11	Rear Door RH	Bent/warped	\$ 1,143.20	X
12	Rear Door Weather Strip RH	1	\$ 398.60	X
13	Rear Door Outer Handle Garnish RH	1	\$ 286.20	X
14	Rear Door Inner Lock RH	1	\$ 486.70	X
15	Front Door RH	1	\$ 1,286.70	X
16	Front Door Weather Strip RH	1	\$ 398.60	X
17	Front Door Outer Handle Garnish RH	1	\$ 275.60	X
18	Rear Lower Arm RH	1	\$ 548.20	X
19	Rear Knuckle Arm RH	1	\$ 670.50	X
20	Rear Hub Bearing RH	1	\$ 386.70	X
21	Rear Upper Arm RH	1	\$ 320.80	X
22	Rear Trailing Arm RH	1	\$ 287.60	X
23	Rear Suspension RH	1	\$ 350.80	X

102

Parts: \$ 10,963.50  
Less Parts 5% : \$ 548.17  
Total Parts : \$ 10,415.32

### Special Net Items :

Rear Fender Sealant	1	\$ 80.00	X
1pce Rear Tyre RH	1	\$ 580.00	X
1pce Rear Sports Rim RH	1	\$ 950.00	680
Rear Bumper Lower Side Garnish (Accessories)	1	\$ 280.00	X
Right Rocker Garnish Set (Accessories)	1	\$ 1,450.00	1000
Total S/N Parts :		\$ 3,340.00	

### Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$ 1,200.00	800
To Putty, Spray Paint on Affected Accident Areas	\$ 1,200.00	800
To Check & Re-Connect all electrical wiring	\$ 50.00	20
To Remove & Install Rear Bootlid Components Trim & Garnish	\$ 150.00	X
To Remove & Install Rear Fenders Trim, Garnish, Spare Tyre Compartment	\$ 150.00	80
To Conduct All Wheel Alignment	\$ 150.00	60
To Remove & Install Rear Undercarriage Components	\$ 250.00	X
To Re-position & Align Reverse Sensor	\$ 120.00	X

To Re-programme & Re-set Diagnostics  
To Conduct Water Leakage Test  
To Rust Proof Affected Areas

11	\$	450.00	X
11	\$	150.00	X
	\$	200.00	60
<b>Total Labour :</b>		<b>\$</b>	<b>4,070.00</b>

<b>TOTAL PARTS :</b>	\$	10,415.32
<b>TOTAL SPECIAL NET ITEM :</b>	\$	3,340.00
<b>TOTAL LABOUR :</b>	\$	4,070.00
<b>TOTAL REPAIR COST :</b>	\$	<u>17,825.32</u>

5695-1

DATE OF SURVEY / INSPECTED:  
RECOMMENDED PART BY PART / LUMP SUM :  
RECOMMENDED NUMBER OF DAYS :  
SURVEY BY / SURVEYOR FIRM :  
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :  
FINALISED AMOUNT :

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 432I

### Vehicle Details

Vehicle No.: SMZ8088D

Vehicle to be Exported: No

Intended Deregistration Date: 11 Aug 2021

Vehicle Make: B.M.W.

Vehicle Model: 116D 5DR LED EU6

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 30735091B37D15A

Chassis No.: WBA1V720705G87184

Maximum Power Output: 85.0 kW (113 bhp)

Open Market Value: \$26,538.00

Original Registration Date: 31 Oct 2017

First Registration Date: 31 Oct 2017

Transfer Count: 2

Actual ARF Paid: \$14,154.00 7077

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Oct 2027

PARF Rebate Amount: \$10,615.00

### Intended COE Rebate Details

COE Expiry Date: 30 Oct 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$41,617.00

COE Rebate Amount: \$25,876.00

**Total Rebate Amount: \$36,491.00**

The information contained herein is correct as at 11 Aug 2021

OK

