



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 1

Our Ref :	WH0780
Vehicle No. :	SMC3822E
Make & Model :	TOYOTA VIOS G (AUTO)

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Boot lid <i>bt</i>		781.00	
2	Boot lid hinge LH/RH@2*\$231 <i>xsu</i>		462.00 X	
1	Boot lid logo badge <i>re</i>		62.00	
1	Boot lid emblem "Vios" <i>re</i>		52.00	
1	Boot lid emblem "G" <i>re</i>		54.00	
1	Boot lid lock <i>bt</i>		379.00 <i>249</i>	
1	Rear bumper <i>de</i>		381.00	
2	Rear bumper side retainer LH/RH@2*\$231 <i>xsu</i>		462.00 X	
2	Tail lamp lower bracket LH/RH@2*\$211 <i>xsu</i>		422.00 X	
1	Rear reinforcement <i>bt</i>		471.00 <i>395</i>	
1	End panel <i>bt</i>		790.00 <i>691</i>	
Part Items Total:			4316.00	
			-25% -1079.00	
			3237.00	
SPECIAL NETT ITEMS				
1	Rear bumper clips <i>re</i>		35.00	
2	Rear Reversor Sensor LH/RH @2*\$380 <i>des</i>		760.00 <i>200</i>	
1	Boot lid insulator clips <i>re</i>		30.00	
1	Rear Car plate with Holder <i>scn</i>		35.00	
1	End Panel Sealant <i>re</i>		60.00 <i>40</i>	
SN Items Total:			920.00	
Total Parts:			4157.00	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH0780
Vehicle No. : SMC3822E
Make & Model : TOYOTA VIOS G (AUTO)

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00 700	} 1490
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00 600	
3	To perform anti-rust treatment on affected areas	60.00 40	
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00 30	
5	To remove and refit rear compartment fitting, trimmings, garnish and etc	100.00 60	
6	To remove and replace rear reverse Sensor	60.00	
Labour Total :		2080.00	
TOTAL (PARTS & LABOUR):		6237.00	

1998.75

340.00

1490.00

3828.75

202

3063

4/8-3,050

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

4p 90010068

6 days

4/8

11/08/21 @ 1410

Resy after repair