



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 1

Our Ref	: WH0780
Vehicle No.	: SMC3822E
Make & Model	: TOYOTA VIOS G (AUTO)

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Boot lid <i>bt</i> ✓		781.00	
2	Boot lid hinge LH/RH@2*\$231 X		462.00	
1	Boot lid logo badge <i>re</i> ✓		62.00	
1	Boot lid emblem "Vios" <i>re</i> ✓		52.00	
1	Boot lid emblem "G" <i>re</i> ✓		54.00	
1	Boot lid lock <i>bt</i> ✓		379.00	
1	Rear bumper <i>de</i> ✓		381.00	
2	Rear bumper side retainer LH/RH@2*\$231 X		462.00	
2	Tail lamp lower bracket LH/RH@2*\$211 X		422.00	
1	Rear reinforcement <i>bt</i> ✓		471.00	
1	End panel <i>bt</i> ✓		790.00	
Part Items Total:			4316.00	
			-25% -1079.00	
			3237.00	
SPECIAL NETT ITEMS				
1	Rear bumper clips <i>re</i> ✓		35.00 ✓	
2	Rear Reversor Sensor LH/RH @2*\$380 <i>des</i> ✓		760.00 200	
1	Boot lid insulator clips <i>re</i> ✓		30.00 ✓	
1	Rear Car plate with Holder <i>sen</i> ✓		35.00 ✓	
1	End Panel Sealant <i>re</i> ✓		60.00 40	
SN Items Total:			920.00	
Total Parts:			4157.00	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref : WH0780

Vehicle No. : SMC3822E

Make & Model : TOYOTA VIOS G (AUTO)

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00 700	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00 600	
3	To perform anti-rust treatment on affected areas	60.00 40	
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00 30	
5	To remove and refit rear compartment fitting, trimmings, garnish and etc	100.00 60	
6	To remove and replace rear reverse Sensor	60.00	
Labour Total :		2080.00	
TOTAL (PARTS & LABOUR):		6237.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
4p 90010068
6 days
4s
11/08/21 @ 1410
Resy after repair