



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/082021/4930

Accident date : 8/8/2021

Your Ref : SHB1046G

Invoice No.:

Date : 10/8/2021

MOTOR CLAIM DEPARTMENT
FIRST CAPITAL INSURANCE LTD

36 Robinson Road
#16-01 City House
Singapore 068877

ESTIMATE COST OF REPAIRS TO

Model : TOYOTA WISH 1.8 A

Vehicle No. : SGP4732C

1	pc	Rear tailgate / <i>6ml</i>	\$ 1,210.40	✓
1	pc	Rear tailgate glass moulding / <i>MC</i>	\$ 97.20	✓
1	pc	Rear tailgate outer chrome garnish X <i>NN</i>	\$ 239.10	
1	pc	Rear tailgate emblem / <i>MC</i>	\$ 50.20	✓
1	pc	Rear tailgate inner trimboard / <i>BR</i>	\$ 328.20	✓
1	pc	Rear tailgate inner lock / <i>Cut</i>	\$ 443.50	✓
1	pc	Rear tailgate rubber / <i>TN</i>	\$ 304.10	✓
1	pc	Rear tailgate RH absorber / <i>X</i> <i>Im</i>	\$ 224.60	
1	pc	Rear tailgate LH absorber / <i>NN</i>	\$ 224.60	
1	pc	Rear RH taillamp / <i>SCPA</i>	\$ 472.60	✓
1	pc	Rear LH taillamp / <i>SCPA</i>	\$ 472.60	✓
1	pc	Rear bumper / <i>re</i>	\$ 470.70	✓
1	pc	Rear bumper RH reflector / <i>Cut</i>	\$ 56.90	✓
1	pc	Rear bumper LH reflector X <i>NN</i>	\$ 56.90	
1	pc	Rear bumper RH side retainer X <i>NN</i>	\$ 57.50	
1	pc	Rear bumper LH side retainer / <i>re</i>	\$ 57.50	✓
2	pcs	Rear bumper side bracket @ \$48.40 X <i>NN</i>	\$ 96.80	
10	pcs	Rear bumper clips @ \$3.00 / <i>MC</i>	\$ 30.00	✓
1	pc	Rear end panel / <i>6ml</i>	\$ 590.60	✓
1	pc	Rear end panel top trim / <i>Cut</i>	\$ 232.90	✓
1	pc	Rear exhaust silencer <i>BT</i>	\$ 798.80	
			\$ 6,515.70	
		Less 25%	\$ (1,628.93)	
			\$ 4,886.78	
1	set	Rear bumper parking sensor / <i>DM</i>	\$ 280.00	N <i>200</i>
1	pc	Rear windscreen gum / <i>MC</i>	\$ 60.00	N

Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/082021/4930

Accident date : 8/8/2021

Your Ref : SHB1046G

1	pc	Rear bumper reverse camera	✓
1	pc	Rear no. plate	✓
		To remove and refix rear windscreen	
		To repair rear damages	
		To spray painting	

Invoice No.:

Date : 10/8/2021

\$ 380.00 N 280

\$ 40.00 N 580

\$ 150.00 120

\$ 780.00 600

\$ 880.00 600

\$ 7,456.78

VIN'S MOTOR PTE LTD

5513.05

-20%: 4400

5 Days.

Inspection

After repair photos.

Gue Riap

10/8/2021

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: