

SJE :	_____	Vehicle Nos :	SMW 7430 X
Date of Survey :	_____	Made :	Honda Civic
Date of ReSurvey:	After-Paint:	Year :	2020
Contacts :	_____	Chassis No :	MRHFC5650LT000391

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:	_____	Working Day:	_____
----------------	-------	---------------------	-------

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Bootlid	1	\$ 789.60	\$ 789.60
2	Bootlid logo	1	\$ 69.50	\$ 69.50
3	Bootlid emblem'Civic'	1	\$ 98.00	\$ 98.00
4	Bootlid emblem 'i-vtec'	1	\$ 98.00	\$ 98.00
5	Bootlid lamp	2	\$ 486.30	\$ 972.60
6	Bootlid inner lock	1	\$ 325.60	\$ 325.60
7	Bootlid lock stricker	1	\$ 68.20	\$ -
8	Bootlid antenna sensor	1	\$ 364.20	\$ 364.20
9	Bootlid buzzer	1	\$ 148.00	\$ 148.00
10	Bootlid inner trim board	1	\$ 304.60	\$ -
11	Bootlid weatherstrip	1	\$ 372.90	\$ 372.90
12	Bootlid outer garnish	1	\$ 348.60	\$ 348.60
13	Bootlid number plate lamp w/switch	1	\$ 155.30	\$ -
14	Bootlid hinge	2	\$ 152.00	\$ 304.00
15	Bootlid reverse camera	1	\$ 488.00	\$ 488.00
16	Rear bumper	1	\$ 895.30	\$ 895.30
17	Rear bumper lower	1	\$ 386.00	\$ 386.00
18	Rear bumper lower chrom garnish	1	\$ 180.00	\$ 180.00
19	Rear bumper side retainer	2	\$ 79.80	\$ 159.60
20	Rear bumper reinforcement	1	\$ 190.80	\$ 190.80
21	Rear bumper bracket	2	\$ 66.00	\$ 132.00
22	Rear bumper reflector	1	\$ 125.40	\$ 125.40
23	Rear bumper reflector garnish	2	\$ 210.90	\$ 421.80
24	Rear bumper reverse sensor	2	\$ 215.00	\$ 430.00
25	Rear end panel	1	\$ 863.70	\$ 863.70
26	Rear end panel top garnish	1	\$ 208.60	\$ 208.60
27	Spare tyre panel	1	\$ 736.90	\$ -
28	Spare tyre panel top board	1	\$ 195.80	\$ -
29	Spare tyre tool tray	1	\$ 155.90	\$ -
30	Rear fender	2	\$ 968.10	\$ -
31	Rear fender inner trim board	2	\$ 298.70	\$ -
32	Taillamp	2	\$ 842.30	\$ 1,684.60
33	Taillamp base panel	2	\$ 289.70	\$ -
Parts Sub Total :				\$ 10,056.80
20% Discount :				\$ 2,011.36
PARTS TOTAL :				\$ 8,045.44

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ -
2	Bootlid sealant	1	\$ 100.00	\$ 30.00
3	Bootlid inner trim board clips	1	\$ 50.00	\$ 20.00
4	Bootlid outer garnish clips	1	\$ 50.00	\$ 20.00
5	Rear bumper clips	1	\$ 50.00	\$ 30.00
6	Rear bumper lower lips	1	\$ 480.00	\$ -
7	Rear bumper reflector garnish clips	2	\$ 50.00	\$ -
8	Rear bumper reverse sensor seal	4	\$ 48.00	\$ -
9	Rear end panel sealant	1	\$ 100.00	\$ 40.00
10	Rear end panel top garnish clips	1	\$ 50.00	\$ 20.00
11	Spare tyre panel sealant	1	\$ 100.00	\$ -
12	Rear fender inner trim board clips	2	\$ 50.00	\$ 40.00
13	Taillamp clips	2	\$ 50.00	\$ 50.00
14	Taillamp seal	2	\$ 60.00	\$ 40.00
15	Taillamp base panel sealant	2	\$ 100.00	\$ -
16	Rear number plate w/casing	1	\$ 80.00	\$ -
SPECIAL NETT TOTAL :				\$ 290.00

Nos.	LABOUR	S\$
1	R&R rear bootlid component	\$ 80.00
2	R&R rear bumper reverse sensor	\$ 60.00
3	R&R reverse camera	\$ 40.00
4	Check wiring	\$ 30.00
5	Upholstery	\$ -
6	Conduct water leakage test	\$ -
7	Diagnostic & reset fault code	\$ 120.00
8	Panel beating	\$ 1,000.00
9	Rust proofing	\$ 80.00
10	Spray Painting	\$ 1,200.00
LABOUR TOTAL :		\$ 2,610.00

(Labour+S/N+Part) = \$10945.40
 Part by part
 Total \$10945.40 and 8 repair days

PARTS TOTAL :	\$	8,045.44
SPECIAL NETT TOTAL :	\$	290.00
LABOUR TOTAL :	\$	2,610.00
GRAND TOTAL :	\$	10,945.44